

ONDA

23/5/2022
Attn: Marcus
WO: 7 days

SERVICE PRE-INVOICE

TOR CO. SDN. BHD.

of the Oriental Holdings Berhad)

oad 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

andra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0080238 / INDIA
Chassis No: JHMGK3850JX210722
License No: SLX1342M
Mileage: 45273
Engine No: L13B11030338

Document No: SVO22024626
Printed By: SUHELMI
Order Date: 31. May 2022
Order Time: 9:33:34 AM
Service Advisor: SUHELMI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO: 77281) OWNER: TAN SOON KEONG OWNER INSURER: SINGAPORE LIFE ACC DATE: 14/05/2022 SURVEYED BY: MARCUS (LKK) DATE: 31/05/2022 REF NO: TP INSURER: INDIA INTERNATIONAL TP VEH: SMP7992C						
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	505.00	25	378.75	26.51	405.26
71505-T5A-J50	GARNISH,RR.BUMPER	1	40.80	25	30.60	2.14	32.74
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	18.00	25	13.50	0.95	14.45
91505-TM8-003	CLIP,BUMPER	1	2.30	25	1.72	0.12	1.84
84640-T5A-003ZA	LINING ASSY,RR.PANEL	1	60.80	25	45.60	3.19	48.79
66100-TAR-T00ZZ	PANEL COMPRR.	1	341.60	25	256.20	17.93	274.13
68100-T5A-U10ZZ	TAIL GATE COMP	1	779.20	25	584.40	40.91	625.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	61.30	25	45.97	3.22	49.19
33550-T5A-J02	TAILLIGHT ASSYL.	1	255.60	25	191.70	13.42	205.12
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	12.20	25	9.15	0.64	9.79
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	7.40	25	11.10	0.78	11.88
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.48	7.30
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
75722-T5L-T01	EMBLEMRR.	1	12.40	25	9.30	0.65	9.95
	SUM PARTS:				1,714.03	119.99	1,834.02
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	120.00	10	108.00	7.56	115.56
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BOJSE	0760	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT.						
BOBC	0760	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BP00R	1845	1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BMI03D	EXT-YJ	1	325.00	10	292.50	20.48	312.98
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BC011R	0760	1	350.00	10	315.00	22.05	337.05
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BG02D	EXT-YJ	1	450.00	10	405.00	28.35	433.35
	REMOVE & INSTALL RR. WINDSCREEN. (N)						

ONDA

SERVICE PRE-INVOICE

OTOR CO. SDN. BHD.

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

er of the Oriental Holdings Berhad)

oad 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

xandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: CU0080238 / INDIA
Chassis No: JHMGK3850JX210722
License No: SLX1342M
Mileage: 45273
Engine No: L13B11030338

Document No: SVO22024626
Printed By: SUHELMI
Order Date: 31. May 2022
Order Time: 9:33:34 AM
Service Advisor: SUHELMI

BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	10	405.00	28.35	433.35
BKRP02B	EXT-YJ KNOCK FLOOR, CUT RR PANEL.STRAIGHTEN FENDERS ALIG RR CHASSIS INCLUDING FIITTING ON ATTACHMENT ITEMS.	1	2,600.00	10	2,340.00	163.80	2,503.80
BP06R	1845 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,340.00	10	2,106.00	147.42	2,253.42
		SUM LABOUR:		6,371.50	446.01	6,817.51	
		TOTAL SGD		8,085.53	566.00	8,651.53	

Total Payable (SGD)

8,651.53

GST Amount is calculated from individual line(s)