PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0413/2022/JT
DATE	:	23-May-22
WIP	:	25145

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON SLG 8865 P

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Thevan
5 days exclude 1 Sunday
Johnny Boo 28 Sep 22

OWNER'S NAME	:	MR TAN JEE CHING
ADDRESS	:	64 FLORA DRIVE #03-54 SINGAPORE 506860
TELEPHONE	:	HP +65 86862032
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100483963-05
VEHICLE NO	:	**SLG 8865 P**
MODEL CODE	:	A3 SEDAN 1.4 TFSI
MODEL YEAR	:	24/9/2016
ENGINE NO	:	CZC 556125
CHASSIS NO	:	WAUZZZ8V5G1099224
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	22-May-22
PLACE OF ACCIDENT	:	TRAFFIC JUNCTION @ TAMPINES ROAD / KPE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLG 8865 P

S/N	NATURE OF JOBS			ESTIMATED CHARGES		*SURVEYOR'S RECOMMENDATIONS*
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N	$	280.00	*$*	*280.00*
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE RENEWAL OF BOTH REAR FENDERS.	S/N	$	600.00		
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N	$	200.00		
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS 1/4 GLASS.	S/N	$	400.00		
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N	$	1,400.00		
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N	$	1,400.00		
	SUB-TOTAL LABOUR CHARGES	:	**$**	**4,280.00**	***$***	***280.00***

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLG 8865 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES		*SURVEYOR'S RECOMMENDATIONS*
	C/F			***$***	***280.00***
7	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	$	4,900.00	***$***	***1,000.00***
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	$	5,000.00	***$***	***1,100.00***
9	**ADDED LABOUR - SEE ATTACHED**	**$**	**1,750.00**	***$***	***800.00***
10	TO CARRY OUT DIAGNOSTIC CHECK. S/N	$	192.00	***$***	***192.00***
	TOTAL LABOUR CHARGES :	**$**	**16,122.00**	***$***	***3,372.00***

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 8865 P

			DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY		S/NETT		*REMARKS*
1	REAR BUMPER	1	$	2,201.00	$	1,760.80
2	REAR BUMPER FIXING PARTS	1	$	201.00		
3	REAR BUMPER GUIDE SECTION - LH / RH	2	$	36.00	$	14.40
4	REAR BUMPER LOCKING MECHANISM	2	$	67.00		
5	REAR BUMPER SPOILER - LH	1	$	264.00	$	210.80
6	REAR LIGHT REFLECTOR - RH	1	$	46.00		
7	TAIL LIGHT OUTER - RH	1	$	974.00	$	778.80
8	TAIL LIGHT TRIM OUTER - RH	1	$	34.00		
9	TAIL LIGHT INNER - RH	1	$	974.00		
10	TAIL LIGHT OUTER - RH	1	$	34.00		
11	REAR BUMPER REINFORCEMENT BEAM	1	$	642.00		
12	REAR BUMPER BRACKET - LH / RH	2	$	30.00		
13	REAR BUMPER GUIDE SECTION - RH LOWER	1	$	75.00	$	59.36
14	REAR VENT TRIM	1	$	75.00		
15	REAR PARKING AID SENSOR - INNER / OUTER	2	$	249.24	$	390.24
16	REAR PARKING AID SENSOR SEAL RING	4	$	10.00	$	8.00
17	REAR BUMPER WIRING SET	1	$	572.00		
18	REAR FENDER - RH	1	$	4,445.00		
19	REAR WINDSCREEN	1	$	905.00		
20	QUARTER WINDOW - RH	1	$	635.00		
	SUB TOTAL SPARE PARTS	:	**$**	**12,469.24**	***$***	***3,222.40***

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 8865 P

			DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY		S/NETT		*REMARKS*
		C/F			*$*	*3,222.40*
21	PRIMER	2	$	44.00		
22	GROMMET	2	$	38.00		
23	FUEL INSERT	1	$	100.00		
24	REAR WHEEL HOUSING LINER - RH	1	$	260.00		
25	ARYLIC SEALANT	S/N	$	180.00		
26	CAVITY WAX	S/N	$	140.00		
27	STONE CHIP	S/N	$	180.00		
28	METAL FILLER POWDER	S/N	$	280.00		
29	REAR WINDSCREEN SEALANT	S/N	$	200.00		
30	1/4 GLASS SEALANT	S/N	$	100.00		
31	SUNDRIES		$	400.00	*$*	*15.68*
	TOTAL SPARE PARTS	:	**$**	**14,391.24**	*$*	*3,238.08*
	TOTAL LABOUR CHARGES	:	**$**	**16,122.00**	*$*	*3,372.00*
	GRAND TOTAL	:	**$**	**30,513.24**	*$*	*6,610.08*

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.
BL-07/09/22

PREMIUM AUTOMOBILES
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept **Tel: 6841 0055 / Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0413/2022/JT 30-Jun-22 CHANG 1 of 1 SLG 8865 P AUDI A3 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REPAIR RHS TAILLAMP PANEL.	$ 700.00	***$ 250.00***
2	TO RESPRAY RHS TAILLAMP PANEL.	$ 1,050.00	***$ 550.00***
	GRAND TOTAL	**$ 1,750.00**	***$ 800.00***

For Premium Automobiles Pte Ltd

Authorised Signature

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT