# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL	**Ref:** CS3/SMO22005349/Kny3e2
50 RAFFLES PLACE #03-03	**Date:** 15/07/2022
SINGAPORE LAND TOWERSINGAPORE 048623	
	Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMU 1458S	**Veh. Inspected**	SLM 33U
Policy No.	D21MTPV01012528	**Coverage ($)**	0.00
Claim No.	CMTD2201933/MYE	**Excess ($)**	0.00
Assign From	GRACE TEO	**Assign Date**	06/06/2022

2. Vehicle Particulars & Condition

Make & Model	FERRARI 458 (A)	**c.c**	4497
Engine No.	HIDDEN	**Year of Reg.**	2011
Chassis No.	ZFF67NHC000178228	**Colour**	RED
Odometer	56013 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/30Z R21	PIRELLI	4 mm
L/H Front Tyre	265/30Z R21	PIRELLI	4 mm
R/H Rear Tyre	325/25Z R21	PIRELLI	4 mm
L/H Rear Tyre	325/25Z R21	PIRELLI	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

5. General Information

Accident Date	31/05/2022	**Inspect Date / Time**	13/06/2022 (02:38 PM)
Survey held at	LIM MOTOR PTE LTD		
	160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $18,000-$25,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/SMO22005349/Kny3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

(signature)

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser