

ASS. REC. BY:

REF:

C12

CS/CTI22005561/Kqc

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. SNM22D204046/C01


Sum Insured: _____ Excess: 250

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 864K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA 5885U

Yr Regn: 04, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS

X-Trail

c.c

1997

Colour: M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 9449

T/Radio: Insured / Std / NI / NA

Eng/No: 133931

C/No: JN1JANT 328 0001775

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: Habited 235/60R18

R: Mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 6 mm

L/Bal. 8 mm

L/Bal. 6 mm

D.O.A. 8/6/22

D.O.I. 13/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/06/22@9.50am revert to Jacqueline Tan via Merimen.

14/06/22@12.16pm Pauline Tham informed C/A via Merimen.

14/06/22@2.54pm Informed Doris C/A on LS basis & ex-\$250 by email.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

: Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

) \$ + RS. \$

) Extras

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 048338
Date calculated: 11/06/2022 12:32 PM

Full Report
Registration: SKA5885U
Printed: 11/06/2022 12:33 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	08/06/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: NISSAN
Model: X-TRAIL (T32/T32R)
Sub Model: BASE MODEL
Model Sheet Number: 71 XT 01
Registration: SKA5885U
VIN number: JN1JANT32Z0001775
Odometer:

Not Notched
1/2y @
Peeling After Paint

Model Specs

FROM 08.2018	AIR CONDITIONING	SHARK AERIAL	LED HEADLAMP
FOG LAMPS	HEADLAMP WASHER	RAIN SENSOR	FOLD SEATS 3RD ROW
WHEEL DICASTAL	RADIAT GRILLE ACTIVE	PARKING ASSISTANT	SILL MOULDINGS ALU
ALLOY MIRROR COVER	SIDE STEP TUBES	ULTRASONIC PARK SYS	1997CCM 140KW
X-TRONIC CVT	VERS GEN COUNTRIES	WHEELS 7J X 18 ALLOY	SPARE WHEEL
CHASS JIG CAROLINER	EMISSION STD EURO 6	HEAD AIRBAG	SILL COVERING ILLUM
TWO COAT METALLIC	PREPARE OFF VEHICLE	CLEAR COAT HARD	

Labour

Code	Description	Time Base 10 WU/h		Price = 42.00 SGD/h	
		WU	Price SGD		
NO NUMBER	JOB ALLOWANCE	5.0	21.00		
1440J1)	R + R FRONT UPPER CROSSMEMBER	7.0	29.40		
	INCLUDES: BUMPER AND RADIATOR				
	REMOVE AND REFIT				
	NOT INCLUDED: BOTH FRONT WINGS AND				
	R + R BOTH HEADLAMPS				
1420J1)	R + R FRONT LOWER CROSSMEMBER	4.0	16.80		
2830A1	LEFT FRONT WING R + R	10.0	42.00		
	INCLUDES: WHEELHOUSE LINER, HEADLAMP				
	AND REQUIRED ATTACHED PARTS R + R				
	NOT INCLUDED : FRONT BUMPER				
	REMOVE AND REFIT				
	ADJUST HEADLAMPS				
NO NUMBER	RENEW R/F CORNER REINFORCEMENT	16.0	67.20		

Code	Description	WU	Price SGD
1610J1)	RENEW R/F WING, UPPER FRONT PANEL CROSSMEMBER AND R/STRUT INCLUDES: R + R COMPLETE FRONT BUMPER, RADIATOR, HEADLAMPS, CONDENSER AND NECESSARY ATTACHED PARTS	46.0	193.20
CD58A1)	R + R RIGHT FRONT AIR GUIDE	5.0	21.00
1010A1	RENEW COMPLETE FRONT BUMPER (REMOVED) INCLUDES: R + R NECESSARY ATTACHED PARTS, RENEW IF NECESSARY	3.0	12.60
UU10A1)	RENEW RADIATOR GRILLE (REMOVED)	1.0	4.20
RE81A1)	RENEW BOTH HEADLAMPS (REMOVED)	1.0	4.20
2990A1	ADJUST HEADLAMPS	2.0	8.40
RE44A1)	RENEW R/F FOG LAMP (REMOVED)	5.0	21.00
CD30A3	R + R LOWER ENGINE PROTECTION	3.0	12.60
UE26A1	RENEW BONNET INCLUDES: CONVERT ALL ATTACHED PARTS AND ADJUST BONNET, APPLY PROTECTIVE WAX	4.0	16.80
1310A1	R + R L/BONNET HINGE (BONNET REMOVED)	1.0	4.20
1311A1	R + R R/BONNET HINGE (BONNET REMOVED)	1.0	4.20
RQ18A1	R + R FRONT AIRBAG SENSOR	6.0	25.20
RG18A1)	R + R WATER RESERVOIR (PUMP)	1.0	4.20
UG10A1	WINDSCREEN R + R INCLUDES: COWL GRILLE, TRIMS A-PILLAR AND REQUIRED ATTACHED PARTS REMOVE AND REFIT DETACH + REFIT FRT HEADLINING (ADD/WORK)	21.0	88.20
4310A1	R + R HEADLINING INCLUDES: R + R NECESSARY ATTACHED PARTS AND TRIMS	29.0	121.80
VK10A1)	R + R LEFT FRONT SEAT BELT	5.0	21.00
VK10A1)	R + R RIGHT FRONT SEAT BELT	5.0	21.00
RQ36A1)	R + R R/SIDE AIRBAG SENSOR	4.0	16.80
RQ32A1)	R + R R/SIDE AIRBAG INCLUDES: R + R SEAT BACKREST COVER	5.0	21.00
VE10A1	R + R RIGHT FRONT SEAT	6.0	25.20
VE13A1)	R + R RIGHT FRONT SEAT BACKREST COVER	1.0	4.20
RQ50A1)	R + R R/HEAD AIRBAG	2.0	8.40
7402A1	RENEW AIRBAG SLIP RING INCLUDES: R + R AIRBAG, STEERING WHEEL AND STEERING WHEEL COVER	11.0	46.20
RQ29A1)	R + R AIRBAG CONTROL UNIT	5.0	21.00
7500A1	R + R INSTRUMENT PANEL INCLUDES: R + R LOWER COVERS, GLOVE BOX, CONTROL LEVER AND ALL NECESSARY ATTACHED PARTS	18.0	75.60
750011	RENEW INSTRUMENT PANEL (REMOVED)	3.0	12.60
2233A1	RENEW RADIATOR (REMOVED)	2.0	8.40
7527A1	R + R HIGH PRESSURE COOLING PIPE	27.0	113.40
1118	R/F WHEELHOUSE REPAIR	20.0*	7 84.00
1208	R/F INN SIDE MEMBER REPAIR	20.0*	7 84.00
1482	RIGHT FRONT DOOR REPAIR	na 10.0*	X 42.00

Labour Cost
Panel / Mechanical Labour

Hrs	WU	
31.50	315.0	1,323.00
Total of Labour		1,323.00

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	23.0	
	R/F WING NEW PART PAINTING	10.0	
	R/F IN CORNER INSERT SURFACE PAINT	4.0	
	FRONT BUMPER NEW PART PAINT K1G	17.0	
	RIGHT FRONT DOOR REPAIR PAINTING <50%	18.0	
	R/F WHEELHOUSE SURFACE PAINT	7.0	
	R/F INN SIDE MEMBER SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	74.30
0742	R/F WING NEW PART PAINTING	21.16
1206	R/F IN CORNER INSERT SURFACE PAINT	1.49
0283	FRONT BUMPER NEW PART PAINT K1G	52.16
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	32.30
1118	R/F WHEELHOUSE SURFACE PAINT	15.69
1208	R/F INN SIDE MEMBER SURFACE PAINT	2.99

Labour Cost - Paint

Factor	Hrs	WU	Price SGD
Time Paint		83.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	116.0	487.20

Material Cost - Paint

	Price SGD
New Part Painting	95.46
New Part Painting - Plastic K1G	52.16
Repair Painting	32.30
Surface-/Blend Paint	20.17
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	241.39

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
0283	FRONT BUMPER	62022 6FS0H	Original	T1	450.00 ✓
0288	R/F BUMPER BRACKET	62222 4CL0A	Original	CNM	55.00 ✓
0295	LOWER BUMPER COVER	62660 4CE1B	Original	R	320.00 ✓
0319	L/F BUMPER REINF	62211 4CL0A	Original	R/R	110.00 ✓

Code	Description	Part Number	Part Source	Price SGD
0320	R/F BUMPER REINF	62210 4CL1A	Original	110.00 X
0333	FRT BUMPER ABSORBER	62090 6FR0A	Original	CM 230.00 ✓
0340	FRT BUMPER SUPPORT	62030 6FV0A	Original	By 390.00 ✓
0344	R/BUMPER COVER	62256 6FLOB	Original	CM 110.00 ✓
0350	FRT BUMPER CLAMP KIT	08543 41042		0.00
0410	GRILLE	62310 6FR0A	Original	RM 360.00 ✓
0414	CTR FRT BUMPER MLDG	62072 6FLOA	Original	RM 160.00 ✓
0417	AIR INTAKE GRILLE	62254 6FR0A	Original	RM 190.00 ✓
0431	RAD GRILLE BADGE	62890 6FLOA	Original	RM 75.00 X
0471	BONNET	F510M 4CCMA	Original	By 700.00 ✓
0475	L/BONNET HINGE	65401 4BA0A	Original	By 70.00 ✓
0476	R/BONNET HINGE	65400 4BA0A	Original	By 70.00 ✓
0483	BONNET MOUNTING KIT	KE980 4C200		0.00
0492	BONNET LOCK	65601 JN01C	Original	K 110.00 ?
0523	L/OUTER SEAL	65810 4CL1C	Original	CM 55.00 ✓
0561	LEFT HEADLAMP ASSY	26060 6FP7B	Original	RM 1,550.00 X
0562	RIGHT HEADLAMP ASSY	26010 6FP7B	Original	CM 1,550.00 ✓
0638	R/F FOG LAMP	26150 8995A	Original	RM 260.00 ✓
0742	R/F WING	F3100 4CCMA	Original	By 380.00 ✓
0790	R/F WING CLAMP KIT	KE980 4C300		0.00
0812	R/F WING BADGE	63890 6FM0A		0.00
0842	R/F WHEELHOUSE COVER	63842 4CB0B	Original	RM 120.00 ✓
0884	R/F WHEELARCH MLDG	63860 4CE0A	Original	RM 180.00 ✓
1001	FRT LWR CROSSMEMBER	62530 4CE0A	Original	By 240.00 ✓
1007	BONNET LOCK BRACKET	62550 7FM0A	Original	K 85.00 X
1017	FRT UPP CROSSMEMBER	62511 4CE0A	Original	195.00 ?
1020	R/RADIATOR BRACKET	62512 4CB0B	Original	90.00 ?
1206	R/F IN CORNER INSERT	64190 4CB0A	Original	By CM 220.00 ✓
1401	WINDSCREEN	72700 6FS3B	Original	CM 720.00 ✓
1411	WINDSCREEN BOND KIT	G2891 89926		0.00
1421	WINDSCREEN MOULDING	72752 4CC0B	Original	RM 90.00 ✓
1431	WINDSCREEN SEAL	G2G16 89900		0.00
1435	W-WASHER BOTTLE	28910 6FP0B	Original	CM 230.00 ✓
4325	PASSENGER AIRBAG	K8515 7FP0A	Original	RM 2,350.00 ✓
4331	INSTRUMENT PANEL	68200 4CE7A	Original	RM 1,350.00 ✓
4465	CONDENSER	92100 4BC5A	Original	RM 680.00 X
4481	COMPR/CONDENSER HOSE	92490 4BC0A	Original	RM 230.00 X
4484	COND/EVAPORATOR HOSE	92440 4BC0A	Original	RM 240.00 X
4590	R/F BACKREST COVER	87620 4BU4A	Original	RM 2,600.00 ✓
4608	R/SIDE AIRBAG	KHEH0 4CB0A	Original	RM 1,550.00 ✓
4611	FRONT AIRBAG SENSOR	K8581 3RA0A	Original	RM 380.00 ✓
4614	R/SIDE AIRBAG SENSOR	K8830 3RA0A	Original	RM 380.00 ✓
4628	R/F HEAD AIRBAG	K85P0 4CU0A	Original	RM 2,200.00 ✓
4661	L/F SEAT BELT	86885 4CF4A	Original	RM 900.00 ✓
4662	R/F SEAT BELT	86884 4CF4A	Original	RM 900.00 ✓
4957	HEADLINING	73910 4BV4A	Original	RM 900.00 ✓
7403	CONTACT RING	B5554 4CE0D	Original	Return 1,300.00 ✓
7440	AIRBAG CONTROL UNIT	K8820 4BE0A	Original	RM 250.00 ✓
7445	AIRBAG UNIT	K8510 4CE1A	Original	RM 1,800.00 ✓
7754	R/F AIR DUCT	21558 6FN0A	Original	RM 2,400.00 ✓
7761	RADIATOR	21460 4BC5A	Original	70.00 ?
7767	ELECTRIC FAN CPL	21481 4BC0A	Original	RM 750.00 X
				RM 750.00 X

Code	Description	Part Number	Part Source	Price SGD
1002	BUZZER	BUZZER	Original	130.00
1003	RH FRONT RELAY BOX	RELAY	Original	120.00
f: OEM Parts				0.00
n: Non-OEM Parts				30,805.00
u: Used parts				100.00
Savings				
Subtotal				30,805.00
Fixed Sundry Parts Price				100.00
Total				30,905.00

Extras

Code	Description	Price SGD
1000	WINDSCREEN SEALANT FRNT WINDSCREEN	60.00*
1001	WINDSCREEN INN SEAL FRNT WINDSCREEN	28.00*
1004	Electrical work Electrical work	50.00*
1005	Engine coolant Engine coolant	30.00*
1006	Front number plate Number Plate	35.00*
1007	Audatex fees Audatex fees	42.00*
1008	PROGRAM AIRBAG ECU AIRBAG	380.00*
Total Extras		625.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	30,805.00	
Total Parts	100.00	30,905.00
Labour Time Base 10 WU/h		
Total 315.0 WU X 42.00 SGD/h	1,323.00	
Total of Labour		1,323.00
Total Of Extras		625.00
Paint Work Time Base 10 WU/h		
Labour Cost 116.0 WU X 42.00 SGD/h	487.20	
Material Cost	241.39	
Total Paint Including Material		728.59
Repair Cost Excludes GST		33,581.59
GST (+7.0%)		2,350.71
Repair Cost Included GST		35,932.30

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/06/2022 16:27 (SGT)
Date of Accident	08/06/2022 19:00 (SGT)
Exact Location of Accident	KPE, Singapore
Additional Location Information	KPE tunnel towards Changi direction
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKA5885U

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Thong Ching Boon
NRIC No	SXXXX580I
Email Address	terthong@gmail.com
Mobile Phone No	(Phone) +65-97707507
Alternative Phone No	(Home) +65-97707507

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	X-trail
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00216222100
Cover Note Number	-

DRIVER

Name of Driver	Thong Ching Boon
NRIC No	SXXXX580I

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

5

4

3

2

1

GIA

X B D

A-5KASPSU

B-57512934

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	580I
Vehicle Details	
Vehicle No.:	SKA5885U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Jun 2022
Vehicle Make:	NISSAN
Vehicle Model:	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	MR20861196B
Chassis No.:	JN1JANT32Z0001775
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,509.00
Original Registration Date:	28 Apr 2016
First Registration Date:	28 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$23,513.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2026
PARF Rebate Amount:	\$15,283.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,970.00
COE Rebate Amount:	\$18,240.00
Total Rebate Amount:	\$33,523.00

The information contained herein is correct as at 09 Jun 2022

OK