

(08/11/13) wef

ASS. REC. BY:

REF:

CCY/ASM 22005585/Rp93

3820

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SFX 972

at Workshop m/s

ARC

of

30, Woonahy / ad PR 61 #05-18

Insured:

ASM

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

68K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFX 972

Yr Regn: 2017 / 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda SHUTTLE 1.5 Hybrid c.c 1496

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

065814

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GP 7112 1161

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/06/22

D.O.I.

14/06/22

Survey held at

ARC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT 38K

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$


) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))





Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-310
DATE : 11-Jun-2022
POLICY NO. : FWD PNPV2021-00003241
VEHICLE REG. NO. : SFX97Z
VEHICLE MAKE : HONDA SHUTTLE 1.5 HYBRID AT

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper <i>de</i>	1	\$ 1,200.00	\$ 1,200.00
2	Front Bumper Clips <i>cm</i>	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer LH <i>X</i>	1	\$ 30.00	\$ 30.00
4	Front Bumper Retainer RH <i>cm</i>	1	\$ 30.00	\$ 30.00
5	Front Bumper Tow Eye Cover <i>X</i>	1	\$ 30.00	\$ 30.00
6	Front Reinforcement <i>?</i>	1	\$ 380.00	\$ 380.00
7	Front Upper Grille Beam Bracket (Center) <i>cm</i>	1	\$ 60.00	\$ 60.00
8	Front Upper Grille (Center) <i>cm</i>	1	\$ 300.00	\$ 300.00
9	Front Upper Grille Chrome <i>cm</i>	1	\$ 280.00	\$ 280.00
10	Front Upper Grille Lower Chrome <i>cm</i>	1	\$ 250.00	\$ 250.00
11	Front Upper Grille Clips <i>cm</i>	6	\$ 5.00	\$ 30.00
12	Front Upper Grille Upper Bracket RH <i>?</i>	1	\$ 30.00	\$ 30.00
13	Front Upper Grille Upper Bracket LH <i>?</i>	1	\$ 30.00	\$ 30.00
14	Front Honda H Emblem with base <i>cm</i>	1	\$ 30.00	\$ 30.00
15	Front Head Lamp RH <i>cm</i>	1	\$ 2,280.00	\$ 2,280.00
16	Front Head Lamp LH <i>cm</i>	1	\$ 2,280.00	\$ 2,280.00
17	Front Head Lamp Bracket RH <i>cm</i>	1	\$ 60.00	\$ 60.00
18	Front Head Lamp Bracket LH <i>X</i>	1	\$ 60.00	\$ 60.00
19	Front Bumper Foglamp Cover Upp RH <i>cm</i>	1	\$ 50.00	\$ 50.00
20	Front Bumper Foglamp Cover Low RH <i>?</i>	1	\$ 100.00	\$ 100.00
21	Air Intake Duct <i>de</i>	1	\$ 60.00	\$ 60.00
22	Support Panel Full Assy <i>lt</i>	1	\$ 580.00	\$ 580.00
23	Support Panel Upper Garnish Cover <i>cm</i>	1	\$ 60.00	\$ 60.00
24	Radiator Side Garnish RH (Air Guide) <i>de</i>	1	\$ 50.00	\$ 50.00
25	Radiator Side Garnish LH (Air Guide) <i>X</i>	1	\$ 50.00	\$ 50.00
26	Radiator <i>lt</i>	1	\$ 1,180.00	\$ 1,180.00
27	Radiator Fan <i>?</i>	1	\$ 70.00	\$ 70.00
28	Radiator Fan Motor <i>?</i>	1	\$ 300.00	\$ 300.00
29	Radiator Fan Shroud <i>?</i>	1	\$ 100.00	\$ 100.00
30	Radiator Spare Tank <i>lt X</i>	1	\$ 40.00	\$ 40.00
31	Radiator Top Bracket RH/LH <i>?</i>	2	\$ 10.00	\$ 20.00
32	A/C Condenser <i>?</i>	1	\$ 880.00	\$ 880.00



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-310
DATE : 11-Jun-2022
POLICY NO. : FWD PNPV2021-00003241
VEHICLE REG. NO. : SFX97Z
VEHICLE MAKE : HONDA SHUTTLE 1.5 HYBRID AT

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
33	A/C Fan ?	1	\$ 70.00	\$ 70.00
34	A/C Fan Motor ?	1	\$ 300.00	\$ 300.00
35	A/C Fan Shroud ?	1	\$ 100.00	\$ 100.00
36	Front Bonnet bt/	1	\$ 900.00	\$ 900.00
37	Front Bonnet Hinge RH bt/	1	\$ 60.00	\$ 60.00
38	Front Bonnet Hinge LH bt/	1	\$ 60.00	\$ 60.00
39	Front Bonnet Insulator de/	1	\$ 140.00	\$ 140.00
40	Front Bonnet Insulator Clip rec/	10	\$ 5.00	\$ 50.00
41	Front Bonnet Lock bt/	1	\$ 120.00	\$ 120.00
42	Front Bonnet Lock Cable cut/	1	\$ 60.00	\$ 60.00
43	Front Bonnet Rubber Seal rec/	1	\$ 60.00	\$ 60.00
44	Front Fender RH bt/	1	\$ 420.00	\$ 420.00
45	Front Fender LH repair	1	\$ 420.00	\$ 420.00
46	Front Fender Shield RH ?	1	\$ 120.00	\$ 120.00
47	Front Fender Shield LH X	1	\$ 120.00	\$ 120.00
48	Front Fender Clip m/	10	\$ 5.00	\$ 50.00
49	Front Wheelhouse Extension Panel RH ?	1	\$ 200.00	\$ 200.00
50	Front Side Frame Gusset Outer Plate RH ?	1	\$ 80.00	\$ 80.00
51	Front Side Frame Gusset Inner Plate RH ?	1	\$ 80.00	\$ 80.00
52	Front Windscreen Cowling m/	1	\$ 360.00	\$ 360.00
53	Front Windscreen Cowling Side Cover RH de/	1	\$ 20.00	\$ 20.00
54	Front Windscreen Cowling Side Cover LH X	1	\$ 20.00	\$ 20.00
55	Front Windscreen ca/	1	\$ 1,900.00	\$ 1,900.00
56	Front Windscreen Upper Moulding rec/	1	\$ 80.00	\$ 80.00
57	Front Windscreen Lower Moulding m/	1	\$ 60.00	\$ 60.00
58	Front Temp Sensor Clip ?	1	\$ 10.00	\$ 10.00
59	Front Wiper Tank de/	1	\$ 110.00	\$ 110.00
60	Front Wiper Tank Neck ?	1	\$ 40.00	\$ 40.00
61	Front Horn (High) X	1	\$ 80.00	\$ 80.00
62	Rear Bumper de/	1	\$ 1,200.00	\$ 1,200.00
63	Rear Bumper Clips m/	10	\$ 5.00	\$ 50.00
64	Rear Bumper Tow Eye Cover cut/	1	\$ 30.00	\$ 30.00
65	Rear Bumper Grille RH X	1	\$ 50.00	\$ 50.00



38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-310
DATE : 11-Jun-2022
POLICY NO. : FWD PNPV2021-00003241
VEHICLE REG. NO. : SFX97Z
VEHICLE MAKE : HONDA SHUTTLE 1.5 HYBRID AT

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

*Resum - Hg 90010068
14 days / 14/06/22 @ 1600
Resum after repair*

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
66	Rear Bumper Grille Inner Bracket RH <i>X</i>	1	\$ 60.00	\$ 60.00
67	Rear Bumper Grille Reflector RH <i>X</i>	1	\$ 50.00	\$ 50.00
68	Rear Tailgate <i>bt</i>	1	\$ 880.00	\$ 880.00
69	Rear Shuttle Emblem <i>new</i>	1	\$ 60.00	\$ 60.00
70	Rear Hybrid Emblem <i>new</i>	1	\$ 70.00	\$ 70.00
71	Rear Windscreen Moulding <i>new</i>	1	\$ 100.00	\$ 100.00
72	Rear End Panel <i>repair</i>	1	\$ 480.00	\$ 480.00
73	Rear End Panel Garnish <i>?</i>	1	\$ 120.00	\$ 120.00
Total Spare Parts				\$ 20,190.00
SPECIAL NETT				
74	Front License Plate with Frame <i>cm</i>	1	\$ 40.00	\$ 40.00 35
75	Front Solar Film <i>new / invisible?</i>	1	\$ 280.00	\$ 280.00 ?
76	Front and Rear Windscreen Sealant <i>new</i>	2	\$ 40.00	\$ 80.00 60
77	Coolant Fluid 4 Litres <i>new</i>	1	\$ 40.00	\$ 40.00
78	Reverse Sensor <i>new</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 640.00
LABOUR				
79	Spray Painting Whole Front and Rear	1	\$ 2,000.00	\$ 2,000.00 1600
80	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 2,000.00	\$ 2,000.00 1400
81	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00 60
82	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00 60
83	Remove, Refit A/C Condenser, Radiator and Refill A/C Gas	1	\$ 100.00	\$ 100.00
84	Remove and Refit Front and Rear Windscreen	2	\$ 120.00	\$ 240.00
85	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00 80
86	Check and Rectify Electrical Wiring	1	\$ 20.00	\$ 20.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Total Labour	\$ 4,620.00
Amount Before Excess	\$ 25,450.00
Add GST @ 7%	1,781.50
Total Amount Payable	\$ 27,231.50

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	11/06/2022 16:51 (SGT)
Date of Accident	10/06/2022 21:40 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	Along CTE towards SLE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFX97Z

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHUA CHER SIAN
NRIC No	SXXXX382D
Email Address	chersian@yahoo.com
Mobile Phone No	(Phone) +65-97649134
Alternative Phone No	+65-97649134

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Shuttle
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	PNPV2021-00003241
Cover Note Number	-

DRIVER

Name of Driver	Goh Yin-Min, Felicia
NRIC No	SXXXX396H

Date Of Birth	13/12/1977
Occupation	Indoor
Date Of Driving Pass	08/05/2002
Driving experience	20 YEARS AND 1 MONTH
Gender	Female
Mobile Number	(Phone) +65-97649134
Alt. Phone Number	-
Email Address	felicia_gohym@yahoo.com
Address	BLK 550 YISHUN AVENUE 6 #04-04
Address complement	-
Postcode	768961
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	Yes

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Refer to Sketch Plan

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7295J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	Chew Ngan Hwee
Contact Number	(Phone) +65-97477477
Address	-
Address complement	-

Postcode		-
Insurance Company Name		-
Nature Of Damage		-
Details of property damaged in accident		-
No. Of Passenger (Including Driver)		-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number		SKC6698B
Vehicle Manufacturer		-
Vehicle Model		-
Vehicle Variant		-
Vehicle Colour		-
Vehicle Category		Private car
Name of Driver		Stanley Hu
Contact Number		(Phone) +65-90300478
Address		-
Address complement		-
Postcode		-
Insurance Company Name		-
Nature Of Damage		-
Details of property damaged in accident		-
No. Of Passenger (Including Driver)		-

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
 (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 (ii) investigating the accident and/or my claims;
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Ca
 Policyholder's Signature / Date & Time
 9:40am 11/6/22
 Sketch Plan

Wlin
 Driver's Signature (If driver is not the policyholder) / Date & Time
 9:40am 11/6/22

[Signature]
 Witnessed by Reporting Centre Personnel



SFX97Z
 Car A - ~~SLE4396M~~
 Car B - SKC6648B
 Car C - SHC 7295J

Describe Circumstances of the Accident

Was driving along CTE. Car B in front jam braked due to other incident in front. Car A braked together. Car C collided into Car A from the rear.

No injuries.

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time
 9:40am 11/6/22


 Driver's Signature (If driver is not the policyholder) / Date & Time
 9:40am 11/6/22


 Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	382D
Vehicle No.:	SFX97Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5 HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	LEB6326096
Chassis No.:	GP71121161
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$23,792.00
Original Registration Date:	13 Oct 2017
First Registration Date:	13 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Oct 2027
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	12 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,189.00
COE Rebate Amount:	\$26,201.00
Total Rebate Amount:	\$29,951.00

The information contained herein is correct as at 14 Jun 2022

OK

Honda Shuttle Hybrid 1.5A

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

88 汽车贸易

MOTOR TRADING



Price **\$68,800**

Depreciation \$12,480 /yr
[View models with similar depreciation](#)

Reg Date 06-Oct-2017
(5yrs 3mths 21days COE left)

Mileage 64,000 km (13.6k /yr)

Manufactured 2017

Road Tax \$682 /yr

Transmission Auto

Dereg Value \$29,780 as of today ([change](#))

Fuel Type Petrol-Electric

COE \$49,000

OMV \$23,792

Engine Cap 1,496 cc

ARF \$5,000

Curb Weight 1,190 kg

Power 101.0 kW (135 bhp)