COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3545A
Make : HYUNDAI
Model : I-40

Date: 06/02/22
Insurance: CHINA TAIPING
MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRT FENDER LH / Panel			$ 663.00	✓
1	FENDER RETAINER LH x NN			$ 24.60	
1	HEADLAMP LH / Cut			$ 1,388.00	✓
1	FRT BUMPER BRACKET TOP LH x SNN			$ 44.80	
1	HEADLAMP SUPPORT PANEL x			$ 907.40	
1	FRT FENDER SHIELD LH / Re			$ 174.90	✓
	SUB TOTAL			$ 3,202.70	
	LESS 20%			$ 640.54	
	DISCOUNTED TOTAL			$ 2,562.16	
					Nett
				$ -	Nett
	Labour Charge				
	PANEL BEATING			$ 600.00	420
	SPRAY PAINTING CHARGE			$ 700.00	500
	TUFF KOTE			$ 60.00	40
	CHECK ALL LIGHTING			$ 60.00	30
	TOTAL LABOUR			$ 1,420.00	
	ESTIMATE TOTAL			$ 3,982.16	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

3612.48

-20%: 2900

30 days.
4/5
After repair photos.
Gus Qi of
4:15 pm
2/6/22

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are [illegible] basis
- Third party [illegible]
- No [illegible]
- Supplementary [illegible] and is subject to [illegible] Insurance Company

Acknowledged by Repairer
Signature:
Date: