Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbro@ymail.com
Tel: 67411730

ESTIMATE

Name: AIG Asia Pacific Insurance Pte Ltd
Addres: Motor Claims Department
78 Shenton Way #07-16
AIG Building Singapore 079120

Ref Date: 24-06-2022
Ref No: GBC4486R220621
Vehicle No: GBC4486R
Model / Make: Toyota Hiace Manual

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Bumper grazed (25%)	$ 465.70	1	$ 465.70		✓
2		Bumper Clips 1 set	$ 48.00	1	$ 48.00	~~SN~~	✓
3		Fender (Body Panel) Rh	$ 1,415.00	1	$ 1,415.00	SN	X
4		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs			$ 600.00		500
5		To putty & spray painting & including touch up paint on accident affectecd areas			$ 500.00		380
6		To apply Rust Proofing , reseal tuff-coating treatment on accident area			$ 40.00		40 X

Total Parts & Labour of estimate for damaged vehicle	$ 3,068.70
Total amount in Lumpsum Basis for repaired vehicle	$ -

SDL

Liu's Bro Auto Engrg Wks

Not Authorised
LKK
27/06/22
Exceeds Authorised
L/S $1000
4 days.

2-513.7
25%
384.27
880
1265.27
202
1012.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: