Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
UEN No: 53291793J liusbro@ymail.com
Tel: 67411730

FINAL BILL

Name: AIG Asia Pacific Insurance Pte Ltd
Address: Motor Claims Department
78 Shenton Way #07-16
AIG Building Singapore 079120

Ref Date: 03/07/2022
Ref No: GBC4486R220621
Vehicle No: GBC4486R
Model / Make: Toyota Hiace Manual

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Bumper	$ 465.70	1	$ 465.70		$ -
2		Bumper Clips 1 set	$ 48.00	1	$ 48.00	SN	$ -
3		Fender (Body Panel) Rh	$ 1,415.00	1	$ 1,415.00	SN	$ -
4		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs			$ 600.00		$ -
5		To putty & spray painting & including touch up paint on accident affectecd areas			$ 500.00		$ -
6		To apply Rust Proofing , reseal tuff-coating treatment on accident area			$ 40.00		$ -

Total Parts & Labour of estimate for damaged vehicle	**$ 3,068.70**
Total amount in Lumpsum Basis for repaired vehicle	$ 1,000.00

SDL One Thousand Only

Liu's Bro Auto Engrg Wks