

Date: 24/06/2022

Vehicle No: SGU9403T

Model: TOYOTA VELLFIRE 2.5Z CVT

Chassis: AGH300040221-2015

Reg.Year: 2016

Third Party Insurer: AIG

Surveyor: GBH2182D

Date of Accident: 23/06/2022

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE 1718	1		Re \$1,985.00
2	REAR TAILGATE "VELLFIRE" EMBLEM	1		Re \$88.00
3	REAR TAILGATE INNER TRIM BOARD	1		Re \$708.00
4	REAR TAILGATE WEATHERSTRIP 352	1		Re \$357.00
5	REAR WINDSCREEN MOULDING	1		Re \$135.00
6	REAR BUMPER 1217	1		Re \$1,800.00
7	REAR BUMPER SIDE BRACKET LH	1		Re \$135.00
8	REAR BUMPER TOWING COVER LH	1		Re \$40.00
9	REAR BUMPER REFLECTOR LH	1		CM \$85.00
10	REAR BUMPER ANTENNA SENSOR	1		CM \$85.00
11	REAR TAIL LAMP LOWER GARNISH COVER LH	1		Re \$325.00
12	REAR TAIL LAMP BRACKET LH	1		CM \$135.00
13	REAR END PANEL 745.20	1		Re \$798.00
14	REAR END PANEL UPPER COVER	1		Re \$170.00
15	REAR FLOOR PANEL TOOLBOX UPPER BOARD	1		Re \$482.00
16	REAR FENDER INNER TRIM BOARD LH	1		Re \$1,772.00
SUB TOTAL				\$9,100.00
LESS 25%				-\$2,275.00
PARTS TOTAL				\$6,825.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		Re \$80.00
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		Re \$50.00
3	REAR BUMPER CLIPS	1		Re \$50.00
4	REAR BUMPER REVERSE SENSOR	1		Re \$300.00
5	REAR END PANEL JOINT SEALANT	1		Re \$100.00
6	REAR END PANEL UPPER COVER CLIPS	1		Re \$40.00
7	REAR FENDER INNER TRIM BOARD CLIPS LH	1		Re \$50.00
S/N TOTAL				\$670.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before S/N Total painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Date:



Date: 24/06/2022
Vehicle No: SGU9403T
Model: TOYOTA VELLFIRE 2.5Z CVT
Chassis: AGH300040221-2015
Reg.Year: 2016

Third Party Insurer: AIG
Surveyor: GBH2182D
Date of Accident: 23/06/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.	\$900.00	600
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR TAIL LAMP LOWER GARNISH COVER LH, REAR END PANEL & ETC.	\$900.00	600
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.	\$150.00	120
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHAINS & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	60
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	50
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	60
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$120.00	X
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$100.00	20

LABOUR TOTAL \$2,540.00

TING AN TOTAL \$10,035.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

