ASS. REC. BY: Kenneth | REF: AIG/ 22008247/Ke | C

ASSIGNMENT

From: ______ Date: ______

Estimated Cost: ______

OD / TP / WS / TP RES / OD RES / EVA / INV / MV (TP circled)

To Inspect Vehicle No: ______

at Workshop m/s Trans Cab

of ______

Insured: ______

Policy No. ______

Claims No. ______

Sum Insured: ______ Excess: ______

(Client's Record)

Make of Veh: ______

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: ______

IDAC Accident Rport: ______ Consistent? : Yes or No

GIA / PR Seen: ______ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: ______ Person Contacted: ______ Vehicle: IN / OUT

Veh No: SHD 5309L Yr Regn: 11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or ______ (Taxi circled)

Make: Toy Prius (A) c.c 1798

Colour: M.P. white / Red A/C: Insured / Std / NI / NA

Sp.Reading 429418 T/Radio: Insured / Std / NI / NA

Eng/No: ______

C/No: JTDKB3FU903076748

Gen. Cond: Good / Fair / Poor / Burnt (Good circled)

Steering: Inorder / Jammed / Leaked / Burnt or ______ (Inorder circled)

Brake: Inorder / Jammed / Leaked / Burnt or ______ (Inorder circled)

Modi: Nil / S/Rim / STD A/Rim or ______ (A/Rim circled)

Tyre Size: F: 195/65R15

R: ——

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Sailun

Front			Rear		
R/Bal.	8	mm	R/Bal.	8	mm
L/Bal.	8	mm	L/Bal.	8	mm

D.O.A. 28/6/22 D.O.I. 29/6/2022

Survey held at ______

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/6	L/Sur @ 1450h Confirm

Date/Time, File Pass to? [ ] : Prell. Report

1) ______ [ ] : Final Report

Date/Time, File Return to?

2) ______

Days Of Repair: ______

Resurvey No. of Trip: ______

Add Fee: [ ] : Site Insp ($ ______)

[ ] : Interview ($ ______)

[ ] : Tech Invs ($ ______)

[ ] : Weekend ($ ______)

Report Format :

Lump Sum / I.B.I: ($ ______)

Survey Fee:	
Transportation:	
___$ + RS.___S/	
Photos	
Others	
TOTAL	

Not Authorised
c/Emp $1450/-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHD5309L

AAD2206-127

29 JUN 2022

Vehicle No.:	**SHD5309L**
Chassis No.:	JTDKB3FU903076748
Co UEN:	200303878K
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS
Date of Accident :	28/06/2022
Third Party Insurer :	**SND8126G/AIG**
Date of Registration :	15/11/2018

	PART		LIST	
1	PANEL SUB-ASSY, REAR DOOR, LH	$	1,294.90	
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	$	193.50	X
1	COVER, REAR DOOR OUTSIDE HANDLE, LH	$	17.90	X
1	HINGE ASSY, REAR DOOR, LOWER LH	$	87.10	
1	HINGE ASSY, REAR DOOR, UPPER LH	$	98.90	
1	TAPE, BLACK OUT, NO.1 REAR LH	$	21.90	
1	TAPE, BLACK OUT, NO.2 REAR LH	$	34.90	
1	TAPE, BLACK OUT, NO.3 REAR LH	$	15.40	
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH	$	926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	$	206.70	X
1	CHECK ASSY, REAR DOOR, LH	$	183.80	X
		TOTAL	**$ 3,081.00**	
		25%	**$ 770.25**	
			$ 2,310.75	

Special Nett

1SET	DOOR WEATHERSTRIP CLIP	$	65.00	X
1	REAR DOOR ADVERTISEMENT	$	200.00	120SN
1	REAR DOOR STICKER TEL. NO	$	100.00	60SN
	TOTAL	**$**	**365.00**	

TOTAL PARTS **$ 2,675.75**

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	$	380.00	X

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G

AAD2206-127

SHD5309L

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	$	1,400.00	200
Putty And Spray Painting Of The Affected Portion.	$	1,400.00	220
To Rust-Proofing and apply undercoat Of The Affected Areas.	$	240.00	30
To Check Electrical Lighting Concerned.	$	170.00	15
TOTAL	**$**	**3,590.00**	
Over All Total	**$**	**6,265.75**	

(PART-BY-PART) Repair Days ~~20~~ days

2days

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: