LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD		Ref:	CS3/AIS22006458/Eqy3
79 ROBINSON ROAD #09-01 SINGAPORE 068897		Date:	06/07/2022
		Code:	AIS

1.	**Policy Particulars :- (THIRD PARTY CLAIM)**			
	Insured Veh.	SJM 2235P	**Veh. Inspected**	FBS 1896B
	Policy No.	SP0001025219	**Coverage ($)**	0.00
	Claim No.	202222005149	**Excess ($)**	0.00
	Assign From	FAIZ ROSLI	**Assign Date**	06/07/2022
2.	**Vehicle Particulars & Condition**			
	Make & Model		**c.c**	0
	Engine No.	HIDDEN	**Year of Reg.**	
	Chassis No.		**Colour**	
	Odometer	-	**Steering**	
	Brakes		**Modification**	
	General			

3.	**Conditions of Tyres**			
		Size	**Make**	**Balance**
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.	**Description of Damages**			
5.	**General Information**			
	Accident Date	06/06/2022	**Inspection Date**	06/07/2022
	Survey held at	BLK 1006 BUKIT MERAH LANE 2 #01-12		
	Repairer	ALBERT MOTOR SUPPLY PTE LTD		
5a.	**Remarks**			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			