Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
UEN No: 53291793J liusbro@ymail.com
Tel: 67411730

ESTIMATE

Name: AIG Asia Pacific Insurance Pte Ltd
Address Motor Claims Department
78 Shenton Way #07-16
AIG Building Singapore 079120

Ref Date: 06-07-2022
Ref No: YN2725J220702
Vehicle No: YN2725J
Model / Make: Hino XZU700R 4.0L Manual Turbo ABS 5T

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Bumper (Safety Bar) Bent	$ 600.00	1	$ 600.00	SN	/ S/N
2		Bumper Bracket Bent	$ 250.00	2	$ 500.00	SN	/ S/N
3	1set	Freezer Box Support Rubber Centre "Big" Torn	$ 250.00	1	$ 250.00	SN	/ S/N
4		Number Plate Panel R	$ 860.00	1	$ 860.00		X
5		Number Plate Lamp (10% Cre	$ 165.00	1	$ 165.00		✓
6		Number Plate "Metal" Bent	$ 28.00	1	$ 28.00	SN	14 S/N
7	Rear Lh	Freezer Box Door Rubber Torn	$ 380.00	2	$ 760.00	SN	1 CX
8		Freezer Box Support Rubber "Small" nn	$ 200.00	1	$ 200.00	SN	X
9		Tail Lamp Cre	$ 270.00	1	$ 270.00		✓
10	Rear Rh	Freezer Box Door Rubber Lower nn	$ 380.00	1	$ 380.00	SN	X
		To remove, replace and realign freezer door panel, fitting and mechanisms			$ 600.00		11
		To check all wiring & electrical component for proper function			$ 40.00		20
		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs			$ 600.00		580
		To putty & spray painting & including touch up paint on accident affectecd areas			$ 600.00		400

Total Parts & Labour of estimate for damaged vehicle	$ 5,853.00
Total amount in Lumpsum Basis for repaired vehicle	

SDL

Liu's Bro Auto Engrg Wks

P-435
10%
P-391.5
S.N-1364
L-1000
2755.50
20%
2204.

Not Authorised
7/7/22
L/S $2200
4 days.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: