MFORT TRANSPORTATION PTE LTD

EPAIR ESTIMATE

Vehicle No. : SHYD6659U
Make : HYUNDAI
Model : IONIQ(G3)

Date: 06/28/22
Insurance: NTUC
MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			$ 459.40
10	REAR BUMPER CLIPS			$ 22.00
1	REAR FENDER RH			$ 1,768.30
1	REAR BUMPER SIDE BRACKET RH			$ 55.80
1	REAR DOOR RH			$ 2,147.90
	SUB TOTAL		22	$ 4,453.40
	LESS 20%			$ 890.68
	DISCOUNTED TOTAL		17.60	**$ 3,562.72**
	REAR DOOR COMFORTDELGRO APP STICKER RH		80.	$ 80.00
				$ 80.00
	Labour Charge			
	PANEL BEATING			$ 1,050.00
	SPRAY PAINTING CHARGE		1275	$ 800.00
	TRANSFER OF DOOR			$ 120.00
	TUFF KOTE			$ 60.00
	REMOVE/ REFIX UPHOLSTERY & CUSHION RR			$ 120.00
	TOTAL LABOUR		1372.60	**$ 2,150.00**
	ESTIMATE TOTAL		2days	**$ 5,792.72**

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 9749 5747
'WP' 28/6/22 @ 430pm
P/P Rear new parts
(2-3 days
taufik@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: