FINAL COST OF REPAIR
(To be completed for only one type of item)

To:	From:	Ref	BB71(1TPTBN)/D/CGTC/011/22
1 TPTBN CHARLIE Unit	93FMD / MOS		

Description of Item:	MAN16.284LAERC			SAF 1222:	SAF 1222 - BB71(1TPTBN)/D/CGTC/011/22
Part/Reg No:	MID20849	Original Value:	-	Date:	15 June 2022
				MO/MR:	8202769646/19870182
Quantity:	01	CE/Non CE:	-	Date:	15 June 2022
				Accident Job No:	8202769646/19870182
				Date:	15 June 2022

Description of Damages and Costs of Repairs:

S/N	Incident Repair	Man-hours
1)	Cargo body reverse camera mounting bracket bent	4.50
1.1)	Remove and refit camera assembly and wire harness to assist in above repair	

S/N	Materials Cost	Unit Price	Qty	COST
				$-
				$-
				$-
				$-
				$-
				$-
				$-

Base/LEO Area Office's Assessment of Damages

Labour Charges @	$79.81	per hour X	4.50	hrs	= $359.15
Total Cost of Parts / Materials Used					= $-
Sub-contractor					= -
Assessment Fee					= $638.47
Towing Service					= $265.24
Total					**$1,262.86**

Estimated Time for Repair:	4.5 Hr

*Delete whichever is not applicable
FINAL COST OF REPAIR

HARI HARAN S/O ANBALAGAN

Digitally signed by HARI HARAN S/O ANBALAGAN
Date: 2022.07.14 16:58:33 +08'00'