ASS. REC BY: Taufik REF: 03/01220070 09/Tqys

ASSIGNMENT

2027 May

From: Date:

Estimated Cost:

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $47K.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

'WP' - PRS'

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: YM 6655 G Yr Regn: 2007 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Isuzu NHR85E c.c 2999

Colour Blue A/C: Insured / Std / Nil / NA

Sp.Reading 996481 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: JAANHR85E77-100127

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/R14

R: " " (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or GT Radial

Front

R/Bal. 6 mm

L/Bal. 6 mm

Rear

R/Bal. 6/6 mm

L/Bal. 6/6 mm

D.O.A.

D.O.I. 25/7/22

Survey held at Aun Joo

Des. of Damages: Ft / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Range: $6000 - $7000, 7 days

Date/Time, File Pass to? 1)

Date/Time, File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. inv's ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format:

Lum Sum / L.B. ...