LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

ATTN: KHOR SAW THENG

Ref: CS3/ASM22007215/Ecy3e2

Date: 18/08/2022

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	SMK 4703S	**Veh. Inspected**	GBB 9323A
	Policy No.	GA565962	**Coverage ($)**	0.00
	Claim No.	S2M047IR	**Excess ($)**	0.00
	Assign From	KHOR SAW THENG	**Assign Date**	28/07/2022

2. Vehicle Particulars & Condition

	Make & Model	NISSAN NV200	**c.c**	1461
	Engine No.	HIDDEN	**Year of Reg.**	2010
	Chassis No.	JN1YBAM20U0003067	**Colour**	WHITE
	Odometer	267123 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	FAIR		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	175/60 R15	DUNLOP	4 mm
	L/H Front Tyre	175/60 R15	DUNLOP	4 mm
	R/H Rear Tyre	175/60 R15	DUNLOP	4 mm
	L/H Rear Tyre	175/60 R15	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



5. General Information

	Accident Date	26/07/2022	**Inspect Date / Time**	29/07/2022 (09:55 AM)
	Survey held at	MILLION AUTO SERVICE 4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $5,000-$6,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**

Report Ref No. CS3/ASM22007215/Ecy3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.