LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CS3/CTI22007371/y3
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date:	02/08/2022
		Code:	CTI

1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	GBL 1427J	**Veh. Inspected**	SJN 206G
	Policy No.		**Coverage ($)**	0.00
	Claim No.	SNM22D205221/C02/CHEESC	**Excess ($)**	0.00
	Assign From	JACQUELINE TAN	**Assign Date**	02/08/2022

2.	Vehicle Particulars & Condition			
	Make & Model		**c.c**	0
	Engine No.	HIDDEN	**Year of Reg.**	
	Chassis No.		**Colour**	
	Odometer	-	**Steering**	
	Brakes		**Modification**	
	General			

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4.	Description of Damages

5.	General Information			
	Accident Date	22/07/2022	**Inspection Date**	
	Survey held at	ACCIDENT ASSIST SG 24 SIN MING LANE, #01-94, MIDVIEW CITY, SINGAPORE 573970		

5a.	Remarks
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.