陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD
1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resubmitted and is subject to approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AIGAsia Insured's Veh No : SGX6171R
Date of Accident : 07 August 2022

Not Authorised
Der
18/08/22
2/S 2400
the photo After repair
4 days

Mr Amal Pravin Nathan Lourdes

Date : 11 August 2022

Estimate To Repair SLC3707S - KIA FORTE K3 1.6A
Chassis No : KNAFZ411MG5600782

S/No	Quantity	Description			Amount	
		LIST ITEMS				
01	1 pc	rear bumper	Dis	688	$ 752.00	
02	~~12 ps~~/set	rear bumper clips ~~@ $5.00~~	nil	50	$ 60.00	
03	1 pc	rear bumper reinforcement	One	341	$ 441.00	
04	1 pc	rear bumper sponge	NF		$ 183.00	X
05	2 ps	rear bumper side retainer @ $25.00	N/S Bent		$ 50.00	1pc
06	2 ps	rear bumper ~~bottom~~ bracket @ 170	TWI		$ 340.00	2pc
07	2 ps	rear bumper top bracket @ $65.00	TWI	35	$ 130.00	1pc
08	1 pc	rear bumper lower cover	Dis	282	$ ~~125.00~~	
09	1 pc	rear end panel	R		$ 692.00	X
10	1 pc	rear end panel inner trim	nil		$ 225.00	X
11	1 pc	bootlid	R		$ 1,298.00	X
12	1 pc	bootlid cerato emblem	nil		$ 65.00	
13	1 pc	bootlid K3 emblem	nil		$ 25.00	
14	1 pc	bootlid centre emblme badge	nil		$ 85.00	X
					$ 4,471.00	
		Less 10 %			$ 447.10	
					$ 4,023.90	
		SPECIAL NETT ITEMS				
15	1 pc	bootlid C&C badge	nil		$ 35.00	X
16	1 set	rear parking sensor	shorted		$ 350.00	200
					$ 385.00	
		LABOUR & MISC. CHARGES				
01		To reinstall of rear bumper parking sensor.			$ 80.00	50
02		To check electrical lighting concerned.			$ 80.00	20
03		To rust-proofing of the affected areas.			$ 150.00	20
04		To transfer of bootlid fittings, attachments and perform water seepage test.			$ nil 80.00	X
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.			$ 650.00	600
06		Putty and spray painting of the affected portion.			$ 700.00	600
					$ 1,740.00	
		Total			$ 6,148.90	1681
						10%
						1512.90
						3002.90