(08/11/13) wef

ASS. REC. BY: Marcus

REF: CC6/A16 22007628/Upa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 7197B

at Workshop m/s

of

Insured: GBJ 46788

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $73k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS $196

Vehicle: IN / OUT

Date: Person Contacted: L1A846038

Veh No: SLE 7197B Yr Regn: 29/07/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA /

Make: Infiniti Q50 c.c 1991

Colour Red A/C: Insured / Std / NI / NA

Sp.Reading 103978 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JNIBCAV37F0480757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or affkd

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	10/08/22	D.O.I.	11/8/22

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt N/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Rq14k. have vides Nott $26962
	Dog lamp missing Daylight lamp mis
11/10/22	4/s $18,000 informed Alan.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ___S + RS, ___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Survey Fee:

Transportation:

TOTAL