COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD8576L
Make : HYUNDAI
Model : I-40

Date: 10/08/2022
Insurance: NTUC
MVA: MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			$ 553.00	
1	REAR BUMPER CLIPS			$ 22.00	
1	REAR BUMPER LOWER COVER			$ 228.00	
1	REAR BUMPER REINFORCEMENT			$ 428.40	
	SUB TOTAL		803	$ 1,231.40	
	LESS 20%			$ 246.28	
	DISCOUNTED TOTAL		642.40	**$ 985.12**	
	REAR BUMPER RUBBER MAT			$ 50.00	Nett
	REAR BUMPER REVERSE SENSOR			$ 135.70	Nett
	REAR FENDER ADVERTISEMENT LOGO LH			$ 100.00	Nett
	REAR FENDER ADVERTISEMENT LOGO RH			$ 100.00	Nett
	REAR BUMPER ADVERTISEMENT LOGO		300	$ 50.00	Nett
				$ 435.70	Nett
	Labour Charge				
	PANEL BEATING			$ 300.00	280
	SPRAY PAINTING CHARGE			$ 300.00	250
	REMOVE/REFIX REVERSE SENSOR		560	$ 60.00	30
	TOTAL LABOUR			**$ 660.00**	
			1502.40		
	ESTIMATE TOTAL		4/s $1200	**$ 2,080.82**	
			02 days		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin 97495747
'up' 6/8/22 @ 430 pm
02 days
c/b Resurvey after repair
tanjin@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: