(08/11/21) wef

ASS. IEC. BY: Rahul

REF: CC3/AIS 22007583/Rcy3

S 220F

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 20744

at Workshop m/s VOLKSWAGEN CTR

of 247, ALEXANDRA RD

Insured: AIS

Policy No.

Claim No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 188K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP 20744 Yr Regn: 2022, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN GOLF 1.5 R-LN c.c 1498

Colour BLUE A/C: Insured / Std / NI / NA

Sp.Reading 3161 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZCDZNW160623

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 17/08/22 D.O.I. 22/08/22

Survey held at VOLKSWAGEN

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or FRT & REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 68K
07/09/2022	Finalised P/P $5,734.49/- and 6 days (Red $7,570.06 / 57%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation: S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)