LKK Auto Consultants Pte Ltd
51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd **27/9/2022**

Survey Details:

Date of loss	7-Sep-22
Date of appointment	9-Sep-22
Date of survey	13-Sep-22
Location of survey	LIM MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	SMW 847Z
Make and Model	BMW 218I LED HL
Date of registration	30/10/2020
Excess	-
Market Value	$ 148,000.00
Parf Rebate	$ 64,062.00
Nett Loss	$ 83,938.00

Repair details:

Initial Estimate	$ -

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	**$ -**
Lump Sum(if applicable)	

Number of days for repair	**3**

LKK Auto Consultants Pte Ltd
51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

The estimate repair cost of the damaged vehicle is in the region of $2,000.00 - $3,000.00.

Mandate:

Liability(TP)	**%**	
Proposed repair cost	$	
Loss of use	$	no. of days
Loss of rental	$	no. of days
Loss of income	$	no. of days
LTA search fees	$	
Others	$	
Proposed Total	**#VALUE!**	