BIFROST AUTO PTE LTD

27/09/2022 @ 1430hrs
Not Auth
1/3 [illegible]
[illegible]

REPAIR ESTIMATE

DATE: 26-Sep-22

INSURANCE: HLA

2kk Auth

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH 9126 U

6 days

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR TRUNK LID COVER Rst	1	$1,303.29	$1,303.29	✓
REAR TRUNK LID LOCK Dam	1	$530.79	$530.79	✓
REAR TRUNK LID LOCK COVER Svc	1	$ 129.80		X
REAR TRUNK LID LOCK SWITCH Hnl	1	$ 468.90		X
REAR TRUNK LID COVER TRIM BOARD Hnl	1	$254.40	$254.40	X
Boot Lid Trimboard,Centre Hnl	1	$159.60	$ 159.60	X
Boot Lid Trimboard SIDE (LH/RH) Hnl	2	$92.50	$ 185.00	X
Boot Lid Trimboard REAR Hnl	1	$124.80		X
BOOT HANDLE Hnl	1	$31.80	$31.80	X
REAR TRUNK LID RUBBER Hec	1	$365.20	$365.20	✓
REAR TRUNK LID GLASS (BLACK COLOR) Hnl	1	$969.70	$969.70	X
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE mainly crack	1	$1,054.71	$1,054.71	✓
REAR TRUNK LID LOGO (PRIUS) Hec	1	$62.14	$62.14	✓
REAR TRUNK LID LOGO (HYBRID) Hec	1	$62.14	$62.14	✓
REAR TRUNK LID LOGO (TOYOTA STAR) Hec	1	$81.43	$81.43	✓
THIRD BRAKE LIGHT Hnl	1	$394.70	$394.70	X
REAR TRUNK LID STRIKER Hnl	1	$98.70	$98.70	X
REAR TRUNK LID HINGE (LH/RH) Hnl	2	$189.50	$379.00	X
REAR TRUNK LID ABSORBER (LH/RH) Hnl	2	$287.50	$575.00	X
REAR TRUNK LID ABSORBER BRACKET (LH/RH) Hnl	2	$127.90	$255.80	X
REAR TRUNK LID STOPPER (LH/RH) Hnl	2	$84.80	$169.60	X
SPOILERSUB-ASSY , REAR Hnl	1	$1,787.79	$1,787.79	X
REAR WINDSCREEN GLASS W/ MOULDING Hnl	1	$1,884.32	$1,884.32	X
ROOF TOP CENTER COVER - BLACK Hnl	1	$956.30	$956.30	X
ROOF TOP GARNISH SUB, LH Hnl	1	$136.80	$136.80	X
ROOF TOP GARNISH SUB, RH Hnl	1	$136.80	$136.80	X
REAR NO. PLATE LAMP LH/RH Hnl	2	$163.50	$327.00	X
REAR BUMPER Repair	1	$503.04	$503.04	✓
REAR BUMPER RE-INFORCEMENT Rst	1	$378.32	$378.32	✓
REAR BUMPER LOWER COVER distorted	1	$654.96	$654.96	✓
REAR BUMPER SIDE RETAINER Svc	2	$112.70	$225.40	X
REAR BUMPER TOWING COVER distorted	1	$82.70	$82.70	✓
REAR BUMPER CLIPS Hec	1	$22.00	$22.00	✓
REAR BUMPER SIDE CLIP Hnl	2	$25.00	$50.00	X
REAR BUMPER UPPER STOPPER (LH/RH) Hnl	2	$76.40	$152.80	X
SEAL, REAR BUMPER SIDE, LH/RH mainly broken	2	$148.40	$296.80	✓
REAR BUMPER UNDER SIDE COVER (LH/RH) Svc	2	$232.00	$464.00	X
ARM SUB-ASSY, REAR BUMPER, (LH/RH) Hnl	2	$139.60	$279.20	X
REAR BUMPER REVERSE SENSOR Dam	1	$235.70	$235.70	✓
TAIL LAMP ASSY (UPPER) crack	2	$557.90	$1,115.80	✓

TAIL LAMP ASSY (LOWER) mounting bracket		2	$570.00	$1,140.00
TAIL LAMP QUARTER PANEL HH		2	$216.00	$432.00
TAIL LAMP SIDE COVER SC		2	$256.00	$512.00
REAR TAILLAMP GUIDE - WHITE HH		1	$95.30	$95.30
REAR END PANEL Dent		1	$738.96	$738.96
REAR END PANEL GARNISH HH		1	$294.80	$294.80
REAR SPARE TYRE PANEL HH		1	$960.80	$960.80
REAR END PANEL GARNISH COVER HH		1	$ 138.90	$138.90
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) HH		1	$668.90	$668.90
REAR FIBER TOOL BOX TRIM (LH/RH) HH		2	$598.00	$1,196.00
REAR FIBER TOOL BOX CENTER HH		1	$186.20	$186.20
SPARE TYRE LOCK NUT HH		1	$88.40	$88.40
SPARE TYRE LOCK NUT BRACKET HH		1	$113.50	$113.50
SPARE TYRE SIDE PANEL (LH/RH) HH		2	$287.30	$574.60
REAR EXHAUST PIPE RH HH		1	$1,163.40	$1,163.40
REAR EXHAUST PIPE HANGER HH		1	$40.70	$40.70
REAR EXHAUST PIPE INSULATOR HH		1	$314.60	$314.60
SUB TOTAL				**$25,281.79**
LESS ~~20%~~ 25%				**$5,056.36**
DISCOUNTED TOTAL				**$20,225.43**
REVERSE CAMERA ASSY HH	SN	1	$380.00	$380.00
REAR TRUNK LOWER W/S MOULDING HH	SN	1	$180.00	$180.00
REAR LOWER W/S SEALANT ~~HH~~ Hec	SN	1	$46.00	$46.00
REAR WINDSCREEN SEALANT Hec	SN	1	$46.00	$46.00
REAR NO. PLATE WITH COVER HH	SN	1	$100.00	$100.00
REAR TRUNK LID APPS STICKER Hec	SN	1	$40.00	$40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER Hec	SN	1	$60.00	$60.00
REAR BUMPER RUBBER MAT original	SN	1	$50.00	$50.00
SUB TOTAL				**$902.00**
Labour Charge				
Panel Beating		1	$1,800.00	$1,~~800.00~~ 600/-
Spray Painting Charge		1	$1,600.00	$1,~~600.00~~ 600/-
Wiring Charge		1	$100.00	$~~100.00~~ 30/-
Tuff Kote		1	$100.00	$~~100.00~~ 40/-
Towing Charge		1	$80.00	$80.00 HH
Remove/Refix Cushion & Upholstery Rear		1	$150.00	$~~150.00~~ 80/-
Remove/Refix Rear Windscreen Glass		2	$120.00	$~~240.00~~ 120/-
Remove/Refix Reverse Sensor		1	$120.00	$~~120.00~~ 40/-
Remove/Refix Exhaust Pipe		1	$80.00	$80.00 HH
Diagnostic & Resetting To Erase Fault Code		1	$550.00	$550.00 HH
TOTAL LABOUR				**$4,820.00**
ESTIMATE TOTAL				**$25,947.43**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date

8,627.98

6,470.98

242.00

1510.00

8222.98

L/S 6,550.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com