Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883
UEN No: 53291793J liusbro@ymail.com
Tel: 67411730

ESTIMATE

Name: Singapore Police Force
Address:

Ref Date: 04-10-2022
Ref No: SMV7045E
Vehicle No: SMV7045E220930
Model / Make: Toyota Hiace High Roof
Capacity: Commuter Turbo Auto

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear Rh	Tail Lamp			$ 386.00		
2		To check all wiring & electrical component for proper function			$ 50.00		
3		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs			$ 300.00		
4		To putty & spray painting & including touch up paint on accident affectecd areas			$ 600.00		

Total Parts & Labour of estimate for damaged vehicle	$ 1,336.00	
Total amount in Lumpsum Basis for repaired vehicle		$ -

SDL

Liu's Bro Auto Engrg Wks