(08/11/13) wef

ASS. REC. BY: Rosm

REF: CS3/SMR 22010057/Rny3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 9442M

at Workshop m/s LIAN HONG SENG

of 5035, AMK Ind Pk 2 #01-345

Insured: SMR

Policy No.

Claims No. TAX/09/22/2079

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBH 9442M Yr Regn: / 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA c.c 2982

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 211701 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFAT354 60K211579

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/R15C

R: 155R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or MAXIMILLER

Front		Rear	
R/Bal.	7 mm	R/Bal.	5/5 mm
L/Bal.	7 mm	L/Bal.	5/5 mm
D.O.A.	29/09/22	D.O.I.	13/10/22

Survey held at LIAN HONG SENG

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11/22 Rasul informed lump sum : $1850 and 3 days

(red, 2650, 59%)

Date/Time, File Pass to?

1) 28/11/2022

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($ 1850)

Survey Fee:

Transportation: S + RS SI

Photos

Others

TOTAL