LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 14 Oct 2022

Preliminary Advice

Vehicle No	: SLP8088T	Accident Date	: 10/10/2022
Make	: AUDI A5	Policy No.	: 2100510066-05
Assignment Date	: 14/10/2022	Excess	: S$0.00
Date of Inspection	: 13/10/2022	Est. Duration of Repair	: 12
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	69,393.00
Revised Amount	:S$	28,921.00
Check Items (Estimated)	:S$	13,157.00
Total	:S$	42,078.00
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	120,000.00
COE / PARF Rebate	:S$	53,105.00
Salvage Value	:S$	
Margin for Repair	:S$	66,895.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .