ASS. REC. BY: Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s C1 M/C

of 322C

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 350L

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $74K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBJ1074D Yr Regn: 01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Toy Dyna c.c 2982

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 144671 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA735Y00K 212226

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: B.S 195R15X8

R: Yoko 155R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	9 mm	R/Bal.	44 mm
L/Bal.	2 mm	L/Bal.	~~44~~ 22 mm
D.O.A.	19/10/22	D.O.I.	10/11/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	

Date/Time, File Pass to? _____

☐ : Prell. Report

☐ : Final Report

Date/Time, File Return to? _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Report Format :

Lump Sum / I.B.I: ($ _____)

Survey Fee: _____

Transportation: _____ $ + RS. _____ SI

Photos _____

Others _____

TOTAL _____

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMCVSNW00003422202
Repairer Reference: 73103
Date calculated: 20/10/2022 4:33 PM

Full Report
Registration: GBJ 1074D
Printed: 20/10/2022 4:33 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMCVSNW00003422202	Date of Incident:	19/10/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	DYNA
Sub Model:	150
Model Sheet Number:	70 1N 03
Registration:	GBJ 1074D
VIN number:	
Odometer:	143150

Not withdrawn
Pending B4 pain
Ex 8350/.
5 days

Model Specs

AIR CONDITIONING	FROM 11.2017	FOG LAMPS	WHEELBASE 3350 MM
SINGLE CAB	3.0 LTR 80KW	TYRES 195/75 R15	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Labour

Time Base 10 WU/h **Price = 42.00 SGD/h**

Code	Description	WU	Price SGD
NO NUMBER	RENEW FRONT PANEL	60.0	252.00
NO NUMBER	R + R BADGE	2.0	8.40
520011)	R + R FRONT BUMPER	4.0	16.80
520011)	RENEW FRONT BUMPER (REMOVED) INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT	2.0	8.40
751011	R + R RADIATOR GRILLE	3.0	12.60
810121Y)	R + R LEFT HEADLAMP (RADIATOR GRILLE REMOVED)	1.0	4.20
810121Y)	R + R RIGHT HEADLAMP (RADIATOR GRILLE REMOVED)	1.0	4.20
810151A	ADJUST HEADLAMPS	3.0	12.60
NO NUMBER	R + R L/F LOWER CLOSING PANEL	1.0	4.20
NO NUMBER	R + R R/F LOWER CLOSING PANEL	1.0	4.20
554011)	R + R WINDSCREEN INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS	14.0	58.80
670051)	R + R LEFT FRONT DOOR	6.0	25.20

Code	Description	WU	Price SGD
670051)	R + R RIGHT FRONT DOOR	6.0	25.20
NO NUMBER	RENEW FRONT CROSSMEMBER	25.0	105.00
743201)	DETACH + REFIT HEADLINING INCLUDES: R + R INSIDE MIRROR, PILLAR TRIMS AND SEAT BELTS	4.0	16.80
NO NUMBER	R + R L/F LOWER DOOR SEAL	2.0	8.40
NO NUMBER	R + R R/F LOWER DOOR SEAL	2.0	8.40
870031)	R + R HEATING CPL	12.0	50.40
NO NUMBER	R + R EVAPORATOR	4.0	16.80
550451)	R + R INSTRUMENT PANEL	9.0	37.80
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)	2.0	8.40
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)	1.0	4.20
850171)	R + R WIPER LINKAGE	1.0	4.20
002019)	DRAIN + REFILL COOLANT	3.0	12.60
441101	R + R STEERING WHEEL	2.0	8.40
002889 ZAX	DRAIN AND REFILL AIR CONDITIONING	7.0	29.40

	Hrs	WU	
Labour Cost			
Panel / Mechanical Labour	17.80	178.0	747.60
Total of Labour			747.60

Paint

Paint Work — **SYSTEM AZT** — **Time Basis 10 WU/h**

Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRONT BUMPER NEW PART PAINTING	12.0	
	L/F BUMPER BRACKET NEW PART PAINTING	6.0	
	R/F BUMPER BRACKET NEW PART PAINTING	6.0	
	FRONT LOWER PANEL NEW PART PAINTING	19.0	
	UPPER FRONT PANEL NEW PART PAINTING	8.0	
	L/F LOWER END PANEL SURFACE PAINT	4.0	
	R/F LOWER END PANEL SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	27.86
0293	L/F BUMPER BRACKET NEW PART PAINTING	1.55
0294	R/F BUMPER BRACKET NEW PART PAINTING	1.55
0414	FRONT LOWER PANEL NEW PART PAINTING	22.00
0418	UPPER FRONT PANEL NEW PART PAINTING	10.32
0889	L/F LOWER END PANEL SURFACE PAINT	0.75
0890	R/F LOWER END PANEL SURFACE PAINT	0.75

Labour Cost - Paint		Hrs	WU	Price SGD
Factor			59.0	
Time Paint	42.00 SGD/h	2.50	25.0	105.00
Preparation Main Work Metal	10 WU/h	8.40	84.0	352.80
Total				

	Price SGD
Material Cost - Paint	
New Part Painting	63.28
Surface-/Blend Paint	1.50
Material-constant Metal Preparation	28.60
Total	93.38

Spare Parts

prices as at 2015-06-01/01

Code	Description	Part Number	Part Source	Price SGD
0485	BADGE MODEL	75311 25100	Original	25.00
0281	FRONT BUMPER	52101 37985	Original	220.00
3010	FRONT CROSSMEMBER	51211 25100	Original	100.00
0414	FRONT LOWER PANEL	55711 37110	Original	450.00
0411	GRILLE	53111 37A01A0	Original	195.00
0293	L/F BUMPER BRACKET	52012 37070	Original	100.00
0561	LEFT HEADLAMP ASSY	81170 37660	Original	300.00
0294	R/F BUMPER BRACKET	52011 37070	Original	100.00
0562	RIGHT HEADLAMP ASSY	81130 37660	Original	300.00
0418	UPPER FRONT PANEL	55078 37110	Original	130.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131		0.00
1410	WINDSCREEN SEAL	56121 25040		0.00
	Savings			0.00
	Subtotal			1,920.00
	Total			1,920.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE	25.00*
	Total Extras	25.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Final Calculation

	SGD	SGD
Parts		
Total Parts	1,920.00	
		1,920.00
Labour Time Base 10 WU/h		
Total 178.0 WU X 42.00 SGD/h		
Total of Labour	747.60	
		747.60
Total Of Extras		
		25.00
Paint Work Time Base 10 WU/h		
Labour Cost 84.0 WU X 42.00 SGD/h	352.80	
Material Cost	93.38	
Total Paint Including Material		
		446.18
Repair Cost Excludes GST		**3,138.78**
GST (+7.0%)		**219.71**
Repair Cost Included GST		**3,358.49**
Deductions (Excludes GST)		
Deduction For Excess	-350.00	
Total Of Deductions (Excludes GST)		**-350.00**
Grand Total Excludes GST		**2,788.78**
GST (+7.0%)		**195.21**
Grand Total Included GST		**2,983.99**

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE
1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/10/2022 17:59 (SGT)
Reported by	Both
Date of Accident	19/10/2022 09:30 (SGT)
Exact Location of Accident	Tampines Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ1074D

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SAFETECH ENGINEERING PTE LTD
Company Reg No	2XXXXX322C
Email Address	hoque.safetech@gmail.com
Mobile Phone No	(Phone) +65-87271633
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNW00003422202

DRIVER

Name of Driver	HOSSAIN MOHAMMAD SHAHADAT
Passport No/FIN	GXXXX606M
Date Of Birth	24/08/1978
Occupation	Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Failure to report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This sketch will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will then be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available thereof.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or processed by my insurer (collectively the "**Personal Information**"), and disclose and transfer such Personal Information to all insurers, the insurers' lawyers, vehicle(s) involved in this accident (all insurers who have insured vehicles involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers, law firms, the Monetary Authority of Singapore and any relevant government bodies/authorities such as the police) for the purposes of:

(i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) communicating and dealing with my instructions or responding to any enquiries by me;

(iv) administering my claim, including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mailing packages; and/or

(v) complying with applicable law in connection with processing, handling and/or dealing with my claims

(collectively the "**Purposes**")

(b) I authorise(s) the insurer(s) involved in this accident and the insurers' lawyers/law firms, third party third party to collect and disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/will be disclosed by any of the insurers and/or GIA to their third party service providers or agents, including the firms which may be situated outside of Singapore, for one or more of the above Purposes.

19/10/2022
12:37PM

19/10/2022
12:37PM

Sketch Plan

SOH JIT HOON

TAMPINES AVENUE 1 ROAD

LORRY
GBJ1074D

CAR
DAMAGE SLE2023C

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	322C

Vehicle Details

Vehicle No.:	GBJ1074D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2836573
Chassis No.:	JTFAT35Y00K212226
Maximum Power Output:	-
Open Market Value:	$27,082.00
Original Registration Date:	02 Jan 2019
First Registration Date:	02 Jan 2019
Transfer Count:	0
Actual ARF Paid:	$1,355.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	$0.00

Intended COE Rebate Details

COE Expiry Date:	01 Jan 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	$27,001.00
COE Rebate Amount:	$16,744.00
Total Rebate Amount:	**$16,744.00**

The information contained herein is correct as at 19 Oct 2022

OK