輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

Date:26/10/2022

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

RE: ACCIDENT INVOLVING SML6902R & SLX7011D ON 13/10/2022
ALONG NORTH BRIDGE ROAD & RAFFLES HOTEL DROP OFF/PICKUP POINT EXIT

SETTLEMENT OF OUR CLAIM FOR SML6902R

Lump Sum Repair cost as recommended by surveyor (TP165)	*$*	*2,942.50*
3 Days Loss of Use @ $80.00 per day	*$*	*240.00*
LTA Insurance Enquiry	*$*	*7.45*
Total	*$*	*3,189.95*

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,
Marco Neo
HUI YANG MOTOR PTE LTD
DID: 64515752
Fax: 64514658
email: hui_yang_motor@hotmail.com

HUI YANG MOTOR PTE LTD

Bill To:

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

TAX INVOICE

TP Claim Invoice No: **TP1065**
Bill Date: **26/10/2022**

	Description	Amount
	Date of Accident : **13/10/2022** Owner : **TAN YONG HENG** Vehicle No : **SML6902R** Make & Model : **HONDA SHUTTLE HYBRID**	
	Lump Sum Repair cost as recommended by surveyor	$ 2,750.00
	Sub-Total :	$ 2,750.00
	Add 7% GST :	$ 192.50
	Total Amount SGD :	**$ 2,942.50**

Reg No.:201629438M
GST No:201629438M

HUI YANG MOTOR PTE LTD

Hui Yang Motor Pte Ltd

Authorised Signature

Hui Yang Motor Pte Ltd
Sin Ming Autocare Blk 176 Sin Ming Drive
#04-02 Singapore 575721
Email: hui_yang_motor@hotmail.com
H/P: 98625891 Office: 64515752 Fax : 64514658

> Back to OneMotoring

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 13 Oct 2022 / 10:34:40
Receipt Date/Time : 13 Oct 2022 / 10:34:40

Tax Invoice/Receipt

Receipt No. : ITNET-00000-221013-000874

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
	Result of Insurance Enquiry - SLX7011D As at 13 Oct 2022/08:30:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.			
1	Insurance Enquiry - SLX7011D Enquiry Fee 20221013103345472244	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20221013103355269	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, Tan Yong Heng hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-09 Sin Ming Autocare Singapore 575721 in all my correspondences with any party in connection with my claim.

Arising from an accident involving my motor vehicle registration number SML 690JR and other vehicles registration number SLX 701D along North Bridge Rd & Raffles Hotel Drop off/ Pickup Point Exit on 13/10/22.

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to negotiate my/our claim on my/our behalf and to execute, sign discharge voucher / indemnity forms and all necessary documents in connection with and arising of the above accident claim.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd.**

.....

Signature of registered owner and/or Company's stamp