Veron Chen (LKKAuto)

From:	Veron Chen (LKKAuto)
Sent:	Friday, 28 October 2022 3:24 PM
To:	ANDY; Taufikh (LKKAuto)
Subject:	RE: GBC 9608Z REPAIR LIMIT-DOA: 21/10/2022 (LONPAC OD)

Dear Andy,

As instructed by our client , please proceed to repair the **insured vehicle GBC 9608A at Lump Sum Repair Not Exceeding $8000 or whichever lower.**

The excess is $500.00 (Section I) and an additional excess of $2,500.00 (Young & Inexperienced Drivers) as the driver has less than
2 years of driving experience.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ANDY <andy@falconair.com.sg>
Sent: Friday, 28 October 2022 1:32 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: GBC 9608Z REPAIR LIMIT

Dear Sir,

We can undertake the repair limit at Lump sum $ 8,000.00
Kindly revert

Best regards,
Andy
Falcon Air Auto Services Pte Ltd
176 Sin Ming Drive #01-06

Sin Ming Autocare
Singapore 575721

Tel: 6452 0880   Fax: 6454 7862

Hi Andy,

Please take note repair limit for this vehicle is $8000, please check and revert if your side can repair this vehicle within the repair limit, so my side can revert to Insurance.

Thank you.

Regards
Taufikh
Lkk Auto