

(08/11/13) Wef

REF:

ASS. REC. BY: Pme

369K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 5413Dat Workshop m/s STRIDESof WARRIORS DEPOTInsured: NTUC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 5413DYr Regn: 2017 1NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID 1800 c.c 1798Colour: MAROONA/C: Insured / Std / NI / NASp. Reading: 401045T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU603575538Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

SAILOR

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 24/10/22D.O.I. 01/11/22

Survey held at

STRIDESDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS \$ _____

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Case Details

Case Reference Number : TAX/10/22/2090
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5413D

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-19704-ID
Assigned By : Wei Siong #

Insurance Company Name : income insurance limited
Accident Date and Time : 29/10/2022 02:15 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, FR BUMPER	1	560.30	560.30	25.00	420.22	Replace	1	420.22	Replace	✓
Standard	Main			SUPPORT, FR BUMPER RH	1	86.20	86.20	25.00	64.65	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT, FR BUMPER LH	1	86.20	86.20	25.00	64.65	Replace	0	0	Not Give	Xan
Standard	Main			COVER, FR BUMPER RH	1	31.80	31.80	25.00	23.85	Replace	0	0	Not Give	Xan
Standard	Main			COVER, FR BUMPER LH	1	31.80	31.80	25.00	23.85	Replace	0	0	Not Give	Xan
Standard	Main			BRACKET, FR BUMPER	1	111.80	111.80	25.00	83.85	Replace	0	0	Not Give	Xan
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	bt ✓
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	cut ✓
Standard	Main			REINFORCEMENT FRONT UPPER	1	773.90	773.90	25.00	580.43	Replace	0	0	Check	?
Standard	Main			ABSORBER, FR BUMPER	1	85.90	85.90	25.00	64.43	Replace	0	0	Check	?
Standard	Main			EXTENSION SUB-ASSY, LH	1	129.90	129.90	25.00	97.43	Replace	0	0	Not Give	Xan
Standard	Main			EXTENSION SUB-ASSY, RH	1	129.90	129.90	25.00	97.43	Replace	0	0	Not Give	Xan
Standard	Main			REINFORCEMENT FRONT LOWER	1	265.90	265.90	25.00	199.42	Replace	0	0	Not Give	Xan
Standard	Main			ABSORBER, FR BUMPER LOWER	1	143.60	143.60	25.00	107.70	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, HOOD TO FR END	1	55.80	55.80	25.00	41.85	Replace	0	0	Not Give	Xan
Standard	Main			EMBLEM ASSY FRONT	1	98.70	98.70	25.00	74.03	Replace	1	74.03	Replace	MIS ✓

Total Spare Part Cost 22,865.64

Surveyor Total 7,057.49

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 18,272.89

Final Sur Total 5,645.99

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation		Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Approval		Remarks	BOM Type
				Part Name								Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			GRILLE, RADIATOR		1	183.90	183.90	25.00	137.93	Replace	0	0	Not Give	Xan
Standard	Main			GRILLE SUB-ASSY		1	374.40	374.40	25.00	280.80	Replace	1	280.80	Replace	Can
Standard	Main			CLIPS PIECE, FRT & RR BUMPER		10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	Can
Standard	Main			RETAINER, FR BUMPER, LH & RH		1	9.50	9.50	25.00	7.13	Replace	0	0	Not Give	Xan
Standard	Main			COVER ASSY, ENGINE		1	201.00	201.00	25.00	150.75	Replace	0	0	Not Give	Xan
Standard	Main			COVER ASSY, ENGINE UNDER CENTER SET		1	511.20	511.20	25.00	383.40	Replace	0	0	Not Give	Xan
Standard	Main			COVER, ENGINE UNDER SIDE RH		1	86.20	86.20	25.00	64.65	Replace	0	0	Not Give	Xan
Standard	Main			COVER, ENGINE UNDER SIDE LH		1	86.20	86.20	25.00	64.65	Replace	0	0	Not Give	Xan
Standard	Main			LAMP ASSY, FOG, RH		1	1,029.90	1,029.90	10.00	926.91	Replace	0	0	Not Give	Xan
Standard	Main			LAMP ASSY, FOG, LH		1	1,029.90	1,029.90	10.00	926.91	Replace	0	0	Not Give	Xan
Standard	Main			UNIT, HEADLAMP, LH		1	2,852.40	2,852.40	10.00	2,567.16	Replace	1	2,567.1	Replace	Can
Standard	Main			UNIT, HEADLAMP, RH		1	2,852.40	2,852.40	10.00	2,567.16	Replace	1	2,567.1	Replace	Can
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1		1	1,039.90	1,039.90	10.00	935.91	Replace	0	0	Not Give	Xan
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1		1	1,039.90	1,039.90	10.00	935.91	Replace	0	0	Not Give	Xan
Standard	Main			HOOD SUB-ASSY		1	1,066.30	1,066.30	25.00	799.72	Replace	0	0	Not Give	Xan
Standard	Main			HINGE ASSY, HOOD, RH		1	63.70	63.70	25.00	47.78	Replace	0	0	Not Give	Xan
Standard	Main			HINGE ASSY, HOOD, LH		1	63.70	63.70	25.00	47.78	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT S/A UPPER,		1	408.50	408.50	25.00	306.38	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT, RADIATOR UPPER RH		1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT, RADIATOR UPPER LH		1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
Standard	Main			FENDER SUB-ASSY, FR, RH		1	1,060.70	1,060.70	25.00	795.53	Replace	0	0	Not Give	Xan
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)		1	59.10	59.10	25.00	44.33	Replace	0	0	Not Give	Xan
Standard	Main			LINER, FR FENDER, RH		1	223.50	223.50	25.00	167.63	Replace	0	0	Not Give	Xan

Total Spare Part Cost 22,865.64

Surveyor Total 7,057.49

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

SMRT Recommendation														Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks			
Standard	Main			FENDER SUB-ASSY, FR , LH	1	1,060.70	1,060.70	25.00	795.53	Replace	0	0	Not Give	Xm			
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	59.10	59.10	25.00	44.33	Replace	0	0	Not Give	Xm			
Standard	Main			LINER, FR FENDER, LH	1	219.10	219.10	25.00	164.33	Replace	0	0	Not Give	Xm			
Standard	Main			COVER, RR BUMPER ASSY	1	478.90	478.90	25.00	359.17	Replace	1	359.17	Replace	de /			
Standard	Main			REAR BUMPER REINFORCEMENT	1	360.10	360.10	25.00	270.08	Replace	0	0	Check	?			
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	new /			
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	new /			
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	new /			
Standard	Main			PAD, RR BUMPER, CTR	3	2.50	7.50	25.00	5.63	Replace	3	5.63	Replace	new /			
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	1	12.30	12.30	25.00	9.23	Replace	1	9.23	Replace	new /			
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0	Not Give	Xm			
Standard	Main			RETAINER, RR BUMPER, RH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give	Xm			
Standard	Main			RETAINER, RR BUMPER, LH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give	Xm			
Standard	Main			SEAL, RR BUMPER , RH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give	Xm			
Standard	Main			SEAL, RR BUMPER , LH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give	Xm			
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	new /			
Standard	Main			GUARD, RR BUMPER, LOWER	1	623.50	623.50	25.00	467.63	Replace	1	467.63	Replace	cut /			
Standard	Main			FILLER, RR BUMPER , RH	1	168.60	168.60	25.00	126.45	Replace	0	0	Not Give	Xm			
Standard	Main			FILLER, RR BUMPER , LH	1	168.60	168.60	25.00	126.45	Replace	0	0	Not Give	Xm			
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	16.70	16.70	25.00	12.52	Replace	1	12.52	Replace	mis /			
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	Xm			
Standard	Main			ANTENNA, ELECTRICAL KEY	1	78.00	78.00	25.00	58.50	Replace	0	0	Not Give	Xm			
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0	Not Give	Xm			

Total Spare Part Cost 22,865.64

Surveyor Total 7,057.49

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 18,272.89

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY ASSY, RR BUMPER, RH	1	544.40	544.40	10.00	489.96	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY ASSY, RR BUMPER, LH	1	544.40	544.40	10.00	489.96	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER, RH	1	189.20	189.20	25.00	141.90	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER, LH	1	261.60	261.60	25.00	196.20	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	249.10	249.10	25.00	186.83	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	1,238.40	1,238.40	25.00	928.80	Replace	1	0	Repair	R
Standard	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	402.50	402.50	25.00	301.88	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	992.30	992.30	25.00	744.22	Replace	1	0	Repair	R
Standard	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	59.10	59.10	25.00	44.33	Replace	1	44.33	Replace	nm
Standard	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	59.10	59.10	25.00	44.33	Replace	1	44.33	Replace	nm
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	nm
Standard	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	nm
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	707.10	707.10	25.00	530.33	Replace	0	0	Not Give	Xm
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	505.50	505.50	10.00	454.95	Replace	0	0	Not Give	Xm
Standard	Main			TAIL GATE LOCK COVER, BACK DOOR	1	32.70	32.70	25.00	24.53	Replace	1	24.53	Replace	nm
Total Spare Part Cost									22,865.64	Surveyor Total 7,057.49				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									18,272.89	Final Sur Total 5,645.99				

1/1/22, 5:15 PM

https://vacswb.smrt.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,014.00	200	
2	Main	TO REPAIR REAR PORTION	1,014.00	400	
Total:			2,028.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0 Xan	
3	Main	TO RESPRAY FRONT HOOD	378.00	0 Xan	
4	Main	TO RESPRAY FRONT FENDER RH	378.00	0 Xan	
5	Main	TO RESPRAY FRONT FENDER LH	378.00	0 Xan	
6	Main	TO RESPRAY REAR BUMPER	378.00	200	
7	Main	TO RESPRAY REAR PANEL	180.00	0 Xan	
8	Main	TO RESPRAY BUMPER BEAM	180.00	0 Xan	
9	Main	TO RESPRAY TAIL GATE	378.00	200	
10	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
Total:			2,988.00	700.00	


Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 Xan	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0 Xan	
4	Main	TO TEST AND REFILL REVERSE SENSOR SYSTEM	120.00	40	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0 Xan	
Total:			600.00	80.00	

Summary

11/1/22, 5:15 PM

https://vacswb.smrt.com.sg/Estimation.aspx

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	18,272.89	5,645.99
Total Labour Cost	2,028.00	600.00
Total Spray Painting	2,988.00	700.00
Other	600.00	80.00
Overall Total	23,888.89	7,025.99
Lump Sum Repair Option	☐	☒
Lump Sum Total	23,900.00	7,050.00
Surveyor Approved Amount		7,050.00
No of Repair Days*	10	5
Remarks		LUMP SUM REPAIR / RESURVEY AFTER REPAIR
Surveyor Name		Rasul
Signature		
Survey Date	01/11/2022	Save Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/11/2022 09:03 (SGT)
Reported by	Driver
Date of Accident	29/10/2022 10:15 (SGT)
Exact Location of Accident	Near CV26+5X Singapore
Additional Location Information	TPE TOWARDS SLE SLIP ROAD EXIT 13
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5413D
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	STRIDES TAXI PTE LTD
Company Reg No	1XXXXX369K
Email Address	Auto-Svcs-TARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

DRIVER

Name of Driver	SHANMUGAVELU S/O RAZANGAM
NRIC No	SXXXX531F
Date Of Birth	14/07/1967
Occupation	Outdoor

Date Of Driving Pass	07/01/2003
Driving experience	19 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	Auto-Svcs-TARC@smrt.com.sg
Address	1
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

PASSENGER 3

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG SLIP ROAD AT THE RIGHT LANE AND HAD STOPPED DUE TO THE FRONT VEHICLE STOPPING WHEN SUDDENLY THE VEHICLE SMS2066T FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY TAXI. DUE TO THE IMPACT. MY TAXI WAS PUSHED FORWARD AND HIT ONTO THE REAR OF THE FRONT VEHICLE SKP8809S. WHEN I ALIGHTED AND CHECKED, I NOTICED THAT THIS WAS A CHAIN COLLISION INVOLVED OF FOUR VEHICLES.

ATTACHMENT(S)

Are accident
Was there

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMS2066T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJJ8112L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKP8809S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore for one or more of the above Purposes



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



D - SKP 88095
A - SHB 5413D
B - SMS 2066T
C - SJJ 8112L

Describe Circumstance of the Accident

Lined area for describing the accident circumstances.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

du 31/10/2022

Witnessed by Reporting Centre Personnel
Name as in NRIC/ID card:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB5413D
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR5109372
Chassis No.:	JTDBK83FU603575538
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025
PARF Rebate Amount:	\$3,750.00

COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$12,913.00
Total Rebate Amount:	\$16,663.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Nov 2022

OK