LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : SKK 4652 D
MAKE : AUDI
MODEL : Q5 2.0 TFSI
YEAR : 2013
CHASSIS NO : WAUZZZ8R8DA101370

DATE : 14-Oct-22
DATE OF ACCIDENT : 12-Oct-22
THIRD PARTY REF SBS 6468 X
THIRD PARTY REF Go Ahead Singapore

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1pc	rear bumper				$ 1,135.90
1pc	rear bumper reinforcement				$ 458.65
1pc	tail gate				$ 3,270.15
1pc	tail gate lamp				$ 1,109.30
1pc	Q5 emblem				$ 72.30
1pc	2.of emblem				$ 72.30
1pc	centre emblem				$ 93.65
					$ 6,212.25
	Less 10%				$ 621.23
					$ 5,591.03
1pc	rear windscreen sealant	S.Nett			$ 40.00
	To putty & spray paint				$ 600.00
	To remove & transfer rear windscreen glass				$ 120.00
	To transfer tail gate fitting.				$ 80.00
	Labour Charges				$ 450.00
TG/VL	TOTAL				$ 6,881.03

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd