LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : SLV 6509 C
MAKE : KIA
MODEL : CERATO K3 1.6A SUNROOF
YEAR : 2018
CHASSIS NO : KNAFZ411MJ5757654

DATE : 10-Nov-22
DATE OF ACCIDENT : 08-Nov-22
THIRD PARTY REF SE 9339 M
THIRD PARTY REF SOMPO INSURANCE (S) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear bumper				$ 639.00
1 pc	Rear bumper reinforcement				$ 313.00
2 pcs	Rear bumper retainer		$ 25.00		$ 50.00
10 pc	Rear bumper clips		$ 3.00		$ 30.00
1 pc	Rear end panel				$ 274.00
1 pc	Rear end panel garnish				$ 58.00
1 pc	Front bumper				$ 639.00
1 pc	Front bumper reinforcement				$ 496.00
1 pc	Front bumper retainer		$ 25.00		$ 50.00
10 pc	Front bumper clips		$ 3.00		$ 30.00
1 pc	Front grille				$ 328.00
2 pcs	Head lamp		$ 2,209.00		$ 4,418.00
					$ 7,325.00
	Less 10%				$ 732.50
					$ 6,592.50
1 set	Rear bumper sensor	S/N			$ 200.00
1 pc	Front no plate	S/N			$ 40.00
	To putty & spray paint				$ 1,200.00
	Paint treatment				$ 600.00
	To check front wiring & focus head lights				$ 35.00
	To anti rust				$ 80.00
	Labour charge				$ 800.00
TG/ZX	TOTAL				$ 9,547.50

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd