# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD	Ref: CS3/ASM22011883/Snp3m4
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811	Date: 23/12/2022
ATTN: TEO KITTY	Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 8140B	Veh. Inspected	SGZ 6611C
Policy No.		Coverage ($)	0.00
Claim No.	S2M04ERR	Excess ($)	0.00
Assign From	TEO KITTY	Assign Date	25/11/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMFD46208S200345	Colour	BLUE
Odometer	190650 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	ECORUN	6 mm
L/H Front Tyre	205/55 R16	ECORUN	6 mm
R/H Rear Tyre	205/55 R16	ECORUN	5 mm
L/H Rear Tyre	205/55 R16	ECORUN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

5. General Information

Accident Date	11/11/2022	Inspect Date / Time	15/12/2022 (04:30 PM)
Survey held at	1 STOP GARAGE PTE. LTD. 55 SERANGOON NORTH AVE 4, #02-10 SINGAPORE 555859		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,500-$4,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/ASM22011883/Snp3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser