



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2301433

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 10/03/2023
Reference CC4/LPC22012126/Rpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SNF 5873S
Insured Veh. SMR 3968P
Claim No. 22/22/22/VP05/026656
Policy No. Z22VP05031843
Accident Date 01/12/2022
Inspection Date 07/12/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC22012126/Rpa3q2 Date: 10/03/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMR 3968P	Veh. Inspected	SNF 5873S	
Policy No.	Z22VP05031843	Coverage (\$)	0.00	
Claim No.	22/22/22/VP05/026656	Excess (\$)	0.00	
Assign From	CHARMAINE KONG	Assign Date	05/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN T-CROSS R-L	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	WVGZZZC1ZNY079015	Colour	GREY	
Odometer	3558 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	PIRELLI	6 mm	
L/H Front Tyre	205/55 R17	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R17	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2022	Inspection Date	07/12/2022	
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 5873S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED REAR BUMPER (UPPER) (SN)	CUT	1,280.79	1,280.79
1	SENSOR BRACKET PRIMED (SN)	NECESSARY	14.79	14.79
1	SENSOR BRACKET PRIMED (SN)	NECESSARY	14.79	14.79
1	SENSOR BRACKET (SN)	NECESSARY	12.92	12.92
1	SENSOR BRACKET (SN)	NECESSARY	12.92	12.92
2	SENSOR BRACKET (SN)	NECESSARY	25.84	25.84
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	68.85	68.85
1	2K-PLASTIC ADHESIVE(SN)	NECESSARY	85.94	85.94
1	SPOILER PRIMED REAR BUMPER (CTR) (SN)	SCRATCHED	320.09	320.09
1	REAR DIFFUSOR SATIN BLACK REAR BUMPER (LOWER) (SN)	SCRATCHED	249.00	249.00
1	BUMPER BRACKET REINFORCEMENT (SN)	NOT NECESSARY	709.97	-
1	ATTACHMENT STRIP BUMPER CTR BRACKET (SN)	NOT NECESSARY	70.05	-
1	GUIDE PIECE LHR BUMPER BRACKET (UPPER) (SN)	NOT NECESSARY	42.59	-
1	GUIDE PIECE RHR BUMPER BRACKET (UPPER) (SN)	NOT NECESSARY	42.59	-
1	GUIDE PIECE LHR BUMPER BRACKET (SIDE) (SN)	NOT NECESSARY	40.20	-
1	GUIDE PIECE RHR BUMPER BRACKET (SIDE) (SN)	NOT NECESSARY	40.20	-
1	REFLECTOR LH (SN)	NOT NECESSARY	81.02	-
			3,112.55	2,085.93
	<u>LABOUR</u>			
	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR .		280.00	280.00
	B&P DIAGNOSIS AND PROGRAMMING .		480.00	480.00
	LABOUR .		2,520.00	800.00
	SPRAY PAINT.		3,360.00	840.00
			6,640.00	2,400.00
	GRAND TOTAL		9,752.55	4,485.93



RECOMMENDED COST OF REPAIRS			4,485.93
-----------------------------	--	--	-----------------

Report Ref No. CC4/LPC22012126/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNF 5873S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNF 5873S

RE-INSPECTION

