LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : SLT 2049 A
MAKE : HYUNDAI
MODEL : ELANTRA AD 1.6 GLS AT
YEAR : 2017
CHASSIS NO : KMHD841CMJU560546

DATE : 14-Dec-22
DATE OF ACCIDENT : 12-Dec-22
THIRD PARTY REF SJU 8379 B
THIRD PARTY REF CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper				$ 474.40
1 pc	o/s front bumper retainer				$ 28.00
1 pc	o/s front headlamp				$ 1,198.80
1 pc	o/s front fender				$ 1,227.70
1 pc	o/s front fender undershield				$ 85.70
1 pc	o/s front lower arm				$ 296.80
1 pc	o/s front knuckle arm				$ 309.40
1 pc	o/s front knuckle bearing with hub				$ 452.80
1 pc	o/s front linkage				$ 89.90
1 pc	o/s front absorber				$ 372.50
1 pc	o/s front absorber mounting				$ 127.00
1 pc	o/s front absorber bearing				$ 89.20
1 pc	steering rack				$ 1,065.00
					$ 5,817.20
	Less 20%				$ 1,163.44
					$ 4,653.76
1 pc	o/s front rims	S.Nett			$ 843.40
1 pc	o/s front wheel cap	S.Nett			$ 120.00
	To putty & spray paint				$ 1,200.00
	To check wheel alingment				$ 80.00
	To remove undercarriage				$ 480.00
	To check wiring & focus head lights.				$ 35.00
	Labour charge				$ 1,200.00
TG/VL	TOTAL				$ 8,612.16

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd