A T AUTO CONSULTANT

Not Authorised
L/Sup @ 325o/n
Recovery After Claim
5days

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 22.12.2022
Vehicle No: SLT2346S
Owner: YEO HWEE LIAN SOPHIA
Date of Accident: 21.12.2022
Make & Model: Honda Vezel
Chassis No : RU11223502

ESTIMATE FOR ACCIDENT VEHICLE NO SLT2346S

PARTS

1	1	Rear bumper 566			Buling	$1,100.00 ✓
2	2	Rear corner panel LH/RH	@	$298.00	Sn	$596.00 ✗
3	2	Rear bumper side retainer LH/RH	@	$59.00	Sn	$118.00 ✗
4	2	Rear bumper reflector LH/RH	@	$151.00	Sn	$302.00 ✗
5	1	Tailgate 953.			Pg	$1,386.00 ✓
6	1	Tailgate reflector LH/RH	@	$412.00	Sn	$824.00 ✗
7	1	Tailgate lock 250.50			Nn	$339.00 ✓
8	1	Tailgate inner trim 250.50			mg CM	$301.00 ? ✓
9	1	Tailgate windscreen seal Pn 112.20			Nn	$385.00 ✓
10	1	Tailgate weatherstrip 298			149Sn	Gn $321.00 50% Sn
11	1	Tailgate emblem "VEZEL"			Nn	$72.00 ✓
12	1	Tailgate moulding			Sn	$422.00 ✗
13	1	Taillamp LH/RH	@	$467.00	Sn	$934.00 ✗
14	1	Taillamp corner panel LH/RH	@	$281.00	Sn	$562.00 ✗
15	1	Rear end panel 411.90			Pg	$556.00 ? ✓
16	1	Rear end panel top garnish 180.90			mg Oil	$286.00 ? ✓
17	1	Rear floor panel			R	$912.00 ✗
18	1	Rear floor panel top garnish			Sn	$378.00 ✗
19	1	Rear floor panel under cover			Sn	$365.00 ✗
20	1	Rear tool box garnish			Sn	$265.00 ✗
21	1	Remote key buzzer			CM	$87.00 ? ✓

SUB TOTAL	**$10,511.00**
LESS 20 %	**$2,138.80**
DISCOUNTED SUB TOTAL	**$8,372.20**

S. NETT ITEM

1	1set	Rear bumper clips	Nn	$50.00 ✓
2	1set	Reverse sensor	Nd/Shen	$330.00 200Sn
3	1set	Rear number plate & garnish	Sn	$100.00 ✗
4	1	Reverse cam	Sn	$180.00 ✗

SUB TOTAL	**$660.00**
LESS 0 %	**$0.00**
DISCOUNTED SUB TOTAL	**$660.00**

LABOUR

1	Panel beating for replace and repair affected parts	$1,200.00	600
2	Spray painting on accident areas	$1,200.00	400
3	Wiring charges	$100.00	15L
4	Apply undercoating to above affected areas	$120.00	30
5	Remove/refix reverse sensor	$50.00	✓
6	Remove/refix tailgate components	$100.00	60
7	Remove/refix tailgate windscreen	$250.00	120

SUB TOTAL (LABOUR) **$3,020.00**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: