ASS. REC. BY: REF: CS/CTI22012858/Avy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLS 1909E

Policy No. DMPCSNW00057902200

Claims No. SNM22D209275/C02/TANCHC

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFD1069D. Yr Regn: 2017, May.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic c.c 1498

Colour: white. A/C: Insured / Std / NI / NA

Sp.Reading: 77435. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHFC1660HT000086

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17.

R: 215/50R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.	25/12/2022	D.O.I.	27/12/22.

Survey held at JEC.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S, U/C.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China
7/2/23	Adrian informed LS $8400 (Red 5132.40, 37%)
	MV :
	PV :
	Nett :
	607J.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 7/2/23-typist

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

Transportation: ___3 + RS___ SI

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Photos

Other

Report Format : Merimen

LS $8400