LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

VEHICLE NO. : YM 7208 H
MAKE : MITSUBSHI
MODEL : FE83BE6SRDEA
YEAR : 2007
CHASSIS NO : FE83BEA10275

DATE : 11-Jan-23
DATE OF ACCIDENT : 19-Dec-22
THIRD PARTY REF YQ 7204 Y
THIRD PARTY REF FIRST CAPITAL INSURANCE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 Pc	Rear Company door wooden panel	S.Nett			$ 800.00
2 Pcs	Rear Company door hinges.	S.Nett	$ 280.00		$ 560.00
	To putty & spray paint.				$ 200.00
	Labour charges.				$ 200.00
TG/VL	TOTAL				$ 1,760.00

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd