DATE: Sn8 Sm | REF:

ASS. REC. BY: PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: AXA

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of Inspection.

N/S	O/S
+/+	

Bal. or Market Value: $140K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 3 days Res: Yes or No

Lump Sum: 25 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMN2285D Yr Regn: 29 JUL 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota noah c.c 1797

Colour Black A/C: Insured / Std / Nil / NA

Sp.Reading 243619 T/Radio: Insured / Std / Nil / NA

Eng/No: –

C/No: ZWR80 - 0395169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / J/Rim, or

Tyre Size: F: 195 / 65 R15

R: 195 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Coloma

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	12/1/23	D.O.I.	17/1/23 2 2opm

Survey held at Lengwang

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Balance: 78.6m
yearly: 20K
MV: 140K
NV: 95K

Date / Time	Action / Instruction
	estimate repair cost /- $2500 - $3500

Simon found COR range should be S$3500 to S$4500 with 5 repair days.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:	
Transportation:	
$ + 10% = $	
Photos	
Others	
TOTAL	

Powered by CamScanner