PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA KHAI@PREMIUMAUTO COM SG / CLAIMS@PREMIUMAUTO COM SG

| | | |
|---|---|---|
| **ESTIMATE** | : | ACCIDENT REPAIRS |
| **WORKSHOP** | : | UBI ROAD 1 |
| **CONTACT NO** | : | 6366 2323 |
| **FAX NO** | : | 6841 1183 |
| **REFERENCE** | : | PA/TP/0132/2023/EQ |
| **DATE** | : | 03-Feb-23 |
| **WIP** | : | 60948 |

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON**

**YOUR INSURED VEH NO : GBC 5839 A**

**SPF ACCIDENT CLAIM SECTION**
LOGISTICS SUPPORT & SERVICES DIVISION
POLICE LOGISTICS DEPARTMENT
POLICE LOGISTICS BASE
1 HEMMANT ROAD
SINGAPORE 438675
Attn: Motor Claims Dept

**Hi Adrian,**
**5 days - ok - Jy - 05 May 23**

| | | |
|---|---|---|
| **OWNER'S NAME** | : | MR CHRISTINE CHAN YIN FUN |
| **ADDRESS** | : | BLK 322 HOUGANG AVENUE 5<br>#09-80<br>SINGAPORE 530322 |
| **TELEPHONE** | : | HP +65 97469183 |
| **TYPE OF CLAIM** | : | THIRD PARTY CLAIM |
| **POLICY NO** | : | 722061736 |
| **VEHICLE NO** | : | **SMN 7022 M** |
| **MODEL CODE** | : | AUDI Q2 1.0 TFSI S-TRONIC |
| **MODEL YEAR** | : | 12/07/2019 |
| **ENGINE NO** | : | CHZ B23440 |
| **CHASSIS NO** | : | WAUZZZGA7KA056950 |
| **MILEAGE** | : | - |
| **DATE IN** | : | - |
| **ESTIMATED BY** | : | JOHNNY BOO / ALLAN WU |
| **ACCIDENT DATE** | : | 28-Jan-23 |
| **PLACE OF ACCIDENT** | : | AFTER PUNGGOL EAST ROAD JUNCTION |

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 7022 M

| S/N | NATURE OF JOBS | | | ESTIMATED CHARGES | | SURVEYOR'S RECOMMENDATIONS |
|---|---|---|---|---|---|---|
| 1 | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. | S/N | $ | 360.00 | $ | 360.00 |
| 2 | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. | S/N | $ | 400.00 | $ | 400.00 |
| 3 | TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY. | S/N | $ | 280.00 | $ | 280.00 |
| 4 | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | | $ | 2,400.00 | $ | 1,600.00 |
| 5 | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS WING MIRROR COVER. | | $ | 3,500.00 | $ | 1,600.00 |
| 6 | TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. | S/N | $ | 280.00 | $ | 280.00 |
| 7 | TO CARRY OUT DIAGNOSTIC CHECK. | S/N | $ | 192.00 | $ | 192.00 |
| | **TOTAL LABOUR CHARGES** | : | **$** | **7,412.00** | $ | 4,712.00 |

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL NORA KHAI@PREMIUMAUTO COM SG / CLAIMS@PREMIUMAUTO COM SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 7022 M

| S/N | PARTS DESCRIPTION | QTY | DAMAGED PARTS & PRICES S/NETT | REMARKS |
|---|---|---|---|---|
| 1 | FRONT BUMPER | 1 | $ 1,008.00 | $ 1,008.00 |
| 2 | FRONT BUMPER AIR GUIDE GRILLE - RH | 1 | $ 200.00 | $ 200.00 |
| 3 | FRONT BUMPER END CAP - RH | 1 | $ 70.00 | |
| 4 | FRONT BUMPER SPOILER | 1 | $ 352.00 | $ 352.00 |
| 5 | FRONT BUMPER CLOSING ELEMENT | 1 | $ 184.00 | |
| 6 | FRONT WHEEL SPOILER | 1 | $ 41.00 | |
| 7 | FRONT BUMPER ADAPTER - RH | 1 | $ 51.00 | |
| 8 | FRONT BUMPER GUIDE SECTION - RH | 1 | $ 43.00 | |
| 9 | FRONT BUMPER TOP COVER | 1 | $ 119.00 | |
| 10 | AIR CONDITIONER STICKER | 1 | $ 9.00 | |
| 11 | CAUTION SIGN STICKER | 1 | $ 17.00 | |
| 12 | FRONT FENDER - RH | 1 | $ 1,360.00 | $ 1,360.00 |
| 13 | FRONT FENDER ATTACHMENT PARTS | 1 | $ 44.00 | |
| 14 | FRONT FENDER BRACE - RH | 1 | $ 62.00 | |
| 15 | FRONT FENDER BRACKET - RH | 1 | $ 60.00 | |
| 16 | FRONT FENDER BRACKET - RH | 1 | $ 19.00 | |
| 17 | HEADLIGHT BRACKET | 1 | $ 27.00 | |
| 18 | FRONT WHEEL HOUSING LINER - RH | 1 | $ 229.00 | |
| 19 | HEADLIGHT MOUNTING - RH | 1 | $ 140.00 | |
| 20 | HEADLIGHT - RH | 1 | $ 5,550.00 | $ 5,550.00 |
| | **SUB TOTAL SPARE PARTS** | : | **$ 9,585.00** | $ 8,470.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA KHAI@PREMIUMAUTO COM SG / CLAIMS@PREMIUMAUTO COM SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 7022 M

| | | | DAMAGED PARTS & PRICES | | | |
|---|---|---|---|---|---|---|
| S/N | PARTS DESCRIPTION | QTY | | S/NETT | | REMARKS |
| | *C/F* | | | | $ | 8,470.00 |
| 21 | HEADLIGHT POWER MODULE - RH | 1 | $ | 876.00 | | |
| 22 | HEADLIGHT HEAT SINK - RH | 1 | $ | 868.00 | | |
| 23 | HEADLIGHT CONTROL UNIT | 1 | $ | 643.00 | | |
| 24 | HEADLIGHT HOSE - RH | 1 | $ | 36.00 | | |
| 25 | LIFT CYLINDER - RH | 1 | $ | 165.00 | $ | 164.50 |
| 26 | LIFT CYLINDER HOSE | 1 | $ | 208.00 | | |
| 27 | FRONT EXTERIOR WING MIRROR MOUNTING | 1 | $ | 1,196.00 | $ | 1,196.00 |
| 28 | FRONT WING MIRROR CAP - RH | 1 | $ | 254.00 | | |
| 29 | FRONT WING MIRROR GLASS - RH | 1 | $ | 341.00 | | |
| 30 | FRONT WHEEL COVER - LH / RH | 2 | $ | 762.00 | $ | 762.00 |
| 31 | FRONT ALUMINIUM RIM - RH | 1 | $ | 1,080.00 | $ | 1,080.00 |
| 32 | FRONT ALUMINIUM RIM RUBBER VALVE | 1 | $ | 4.00 | $ | 3.80 |
| 33 | SUNDRIES | | $ | 400.00 | $ | 28.00 |
| | **TOTAL SPARE PARTS** | : | **$** | **16,418.00** | $ | 11,704.30 |
| | **TOTAL LABOUR CHARGES** | : | **$** | **7,412.00** | $ | 4,712.00 |
| | **GRAND TOTAL** | : | **$** | **23,830.00** | $ | 16,416.30 |

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.
BL-03/05/23