Not Authorised
L/Pay &
Pay After Paint
4days

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z
Address: 60 JALAN LAM HUAT,CARROS CENTRE #05-68 S737986
HP: 98888885

Estimation

Date: 7/2/2023
Vehicle: SMY9913X
Make / Model: TOYOTA PRIUS
INSURANCE

No.	Description		Unit	Unit Price	Amount	
1	TAILGATE	Rp	1	$ 1,359.00	$ 1,359.00	✓
2	TAILGATE LOGO	New	1	$ 95.50	$ 95.50	✓
3	TAILGATE EMBLEM PRIUS t	New	1	$ 89.40	$ 89.40	✓
4	TAILGATE EMBLEM HYBRID	New	1	$ 82.30	$ 82.30	✓
5	TAILGATE WEATHERSTRPE	Rn	1	$ 212.00	$ 212.00	X
6	TAILGATE DETECTOR	Rn	1	$ 321.00	$ 321.00	X
7	REAR BUMPER	Rn	1	$ 658.00	$ 658.00	✓
8	REAR BUMPER SIDE RETAINER	C/S Dry	2	$ 112.00	$ 224.00	✓
9	REAR BUMPER REINFORCEMENT		1	$ 350.50	$ 350.50	?
10	REAR BUMPER LIP	Nd/Rn	1	$ 728.90	$ 728.90	X
11	REAR BUMPER REFLECTOR	Rn	2	$ 68.00	$ 136.00	X
12	REAR BUMPER UNDERCOVER GARNISH	Dry	1	$ 321.00	$ 321.00	✓
13	REAR END PANEL	R	1	$ 612.00	$ 612.00	X
14	REAR END PANEL TOP GARNISH	Rn	1	$ 212.00	$ 212.00	X
16	REAR FLOOR PANEL TOP BOARD	Rn	1	$ 398.00	$ 398.00	X
					$ 5,799.60	
				Less 20%	$ 1,159.92	
				Total	$ 4,639.68	
	S/Nett items:					
1	REAR BUMPER CLIPS	New	1	$ 80.00	$ 80.00	50 wa
2	REAR REVERSE SENSOR	C M	1	$ 250.00	$ 250.00	200 wa
3	REAR END PANEL TOP GARNISH CLIPS	~	1	$ 80.00	$ 80.00	X
4	REAR END PANEL SEALANT	~	1	$ 60.00	$ 60.00	X
					$ 470.00	
	Labour to: REAR					
1	TO CHECK REAR ELECTRICAL WIRING		1	$ 150.00	$ 150.00	2 d
2	TO REMOVE AND RENEW REVERSE SENSOR		1	$ 150.00	$ 150.00	5 d
3	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY		1	$ 200.00	$ 200.00	5 d
4	APPLY ANTI RUST ON AFFECTED AREAS		1	$ 100.00	$ 100.00	3 d
5	SPRAY PAINTING ON AFFECTED AREAS		1	$ 800.00	$ 800.00	6 d
6	PANEL BEATING ON AFFECTED AREAS		1	$ 800.00	$ 800.00	5 d
					$ 2,200.00	

Parts Replacement Amount	$ 5,109.68
Total Amount for Labour	$ 2,200.00
Total Amount	$ 7,309.68