

(08/11/13) wef

ASS. REC. BY:

REF:

5322

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SKL 1173J

at Workshop m/s

PREMIUM

of

24, Bhami SECTOR

Insured:

A15

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

247K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

REPAIR LIMIT - 96K

Veh No:

SKL 1173J

Yr Regn:

2022 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A6 DESIGN 2.0TFSI c.c. 1984

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading

7817

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU222 F20NP 006334

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

02/02/23

D.O.I.

06/02/23

Survey held at

PREMIUM

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format :

☐

: Interview (\$

☐

: Tech. Invs (\$



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0137/2023/EQ
DATE : 6-Feb-23
WIP : 61629

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAU KIAN KOON
ADDRESS : 28 FLORA DRIVE
#07-58
SINGAPORE 506951
TELEPHONE : HP +65 98211159
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220130725
VEHICLE NO : **SKL 1173 J**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 16/11/2022
ENGINE NO : DKY 016361
CHASSIS NO : WAUZZZF20NN006334
MILEAGE : 7,816
DATE IN : 3-Feb-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Feb-23
PLACE OF ACCIDENT : TPE TOWARDS CHANGI, BEFORE PUNGGOL EAST FLYOVER,
IN FRONT OD GLOBAL INDIA INTERNATIONAL SCHOOL.
COORDINATES: 1.39591, 103.90511

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 1173 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 / 500	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00 ?	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 ?	
5	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 X	
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00 / 1000	
TOTAL LABOUR CHARGES		: \$ 11,040.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 1173 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS.	\$ 7,500.00	1260
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 18,732.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 11731

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de/</i>	1	\$	3,187.00
2	FRONT BUMPER FIXING PARTS ?	1	\$	689.00
3	FRONT BUMPER CLOSING ELEMENT - CENTER ?	1	\$	263.00
4	FRONT BUMPER ADAPTER - LH / RH ?	2	\$	94.00
5	FRONT BUMPER REINFORCEMENT - LH / RH ?	2	\$	264.00
6	FRONT BUMPER GRILLE - LOWER CENTRE X	1	\$	181.00
7	FRONT BUMPER CLOSING ELEMENT - LOWER X	1	\$	248.00
8	FRONT BUMPER SPOILER ? X ?	1	\$	298.00
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH X	2	\$	1,026.00
10	FRONT BUMPER AIR GUIDE - LH / RH X	2	\$	78.00
11	FRONT BUMPER AIR GUIDE - LH / RH X	2	\$	62.00
12	RADIATOR GRILLE <i>cm-</i>	1	\$	2,603.00
13	RADIATOR GRILLE COVER ?	1	\$	65.00
14	RADIATOR GRILLE COVER CAP <i>cm-</i>	1	\$	59.00
15	RADIATOR GRILLE BRACKET ?	1	\$	111.00
16	FRONT PARKING AID SENSOR - INNER / OUTER ?	4	\$	1,196.00
17	FRONT PARKING AID SEAL RING <i>de/</i>	4	\$	11.00
18	FRONT BUMPER WIRING SET ?	1	\$	648.00
19	FRONT BUMPER FOAM FILLER PIECE <i>cm-</i>	1	\$	267.00
20	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$	1,140.00
SUB TOTAL SPARE PARTS		:	\$	12,490.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 11731

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BUMPER SUPPORT - LH / RH <i>cm / ?</i>	2	\$	71.00	
22	FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$	106.00	
23	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$	130.00	
24	FRONT BUMPER TOP COVER <i>dr /</i>	1	\$	149.00	
25	AIR CONDITIONER STICKER <i>new /</i>	1	\$	36.00	
26	CAUTION SIGN STICKER <i>new /</i>	1	\$	17.00	
27	HORN LOW TONE - LH <i>?</i>	1	\$	244.00	
28	HORN HIGH TONE - RH <i>?</i>	1	\$	157.00	
29	HORN BRACKET - LH / RH <i>?</i>	2	\$	112.00	
30	FRONT FENDER - LH / RH <i>?</i>	2	\$	3,492.00	
31	FRONT FENDER BRACE - LH / RH <i>?</i>	2	\$	292.00	
32	FRONT FENDER BRACKET - LH / RH UPPER <i>?</i>	2	\$	104.00	
33	FRONT WHEEL HOUSING LINER - LH / RH <i>X</i>	2	\$	644.00	
34	FRONT WHEEL SPOILER - LH / RH <i>X</i>	2	\$	392.00	
35	FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH <i>?</i>	2	\$	120.00	
36	FRONT WHEEL SPOILER TRIM BRACKET - LH / RH <i>?</i>	2	\$	96.00	
37	BONNET HOOD SEAL COVER - LH / RH <i>?</i>	2	\$	84.00	
38	BONNET LOCK COVER - LH / RH <i>cm /</i>	2	\$	104.00	
39	BONNET <i>bt /</i>	1	\$	5,971.00	
40	BONNET HINGE - LH / RH <i>bt /</i>	2	\$	406.00	
SUB TOTAL SPARE PARTS		:	\$	12,727.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 1173 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET ATTACHMENT PARTS ?	1	\$ 259.00	
42	BONNET IMPACT PROTECTION - LH / RH / CENTER <i>na</i>	3	\$ 99.00	
43	BONNET STRIKER - LH / RH ?	2	\$ 260.00	
44	BONNET LOCK - LH / RH ?	2	\$ 488.00	
45	BONNET RELEASE ELEMENT ?	1	\$ 69.00	
46	BONNET RELEASE LEVER <i>X</i>	1	\$ 16.00	
47	BONNET BOWDEN CABLE - CENTER ?	1	\$ 67.00	
48	BONNET RELEASE CABLE COVER ?	1	\$ 12.00	
49	HEADLIGHT MOUNTING - LH / RH ?	2	\$ 280.00	
50	HEADLIGHT - LH / RH <i>cm</i>	2	\$ 19,424.00	
51	HEADLIGHT HOSE - LH / RH ?	2	\$ 68.00	
52	LIFT CYLINDER - LH / RH ?	2	\$ 460.00	
53	LIFT CYLINDER BRACKET - LH / RH ?	2	\$ 16.00	
54	LIFT CYLINDER HOSE ?	1	\$ 208.00	
55	LOCK CARRIER ?	1	\$ 1,448.00	
56	LOCK CARRIER SUPPORT - LH / RH ?	2	\$ 52.00	
57	CHARGE AIR COOLER <i>H</i>	1	\$ 692.00	
58	CHARGE AIR COOLER PRESSURE HOSE - RH ?	1	\$ 354.00	
59	CHARGE AIR COOLER PRESSURE PIPE - LH ?	1	\$ 434.00	
60	A/C CONDENSER WITH DRYER ?	1	\$ 724.00	
SUB TOTAL SPARE PARTS		:	\$ 25,430.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 1173 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	A/C CONDENSER REFRIGERANT LINE ?	1	\$	293.00
62	A/C CONDENSER REFRIGERANT LINE ?	1	\$	312.00
63	A/C CONDENSER REFRIGERANT LINE ?	1	\$	293.00
64	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$	27.00
65	RADIATOR ?	1	\$	1,103.00
66	READY-MIX COOLANT ?	6	\$	326.00
67	RADIATOR FAN RING ?	1	\$	318.00
68	RADIATOR FAN WITH CONTROL UNIT ?	1	\$	2,131.00
69	RADIATOR AIR GUIDE - LH / RH ?	2	\$	100.00
70	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$	78.00
71	RADIATOR INTAKE AIR DUCT ?	1	\$	54.00
72	RADIATOR INTAKE AIR DUCT ?	1	\$	98.00
73	RADIATOR AIR FILTER ?	1	\$	348.00
74	RADIATOR INTAKE HOSE ?	1	\$	180.00
75	AIR MASS METER ?	1	\$	639.00
76	FRONT WATER DEFLECTOR STRIP - LH / RH X	2	\$	140.00
77	FRONT WINDOW GUIDE CHROME TRIM STRIP - LH / RH X	2	\$	608.00
78	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH / RH X OUTER	2	\$	474.00
79	FRONT NUMBER PLATE 54 /	S/N	\$	60.00
80	SUNDRIES ?		\$	500.00
TOTAL SPARE PARTS			:	\$ 58,729.00
TOTAL LABOUR CHARGES			:	\$ 18,732.00
GRAND TOTAL			:	\$ 77,461.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasul - Hp 90010068
: 06/02/23 P1540
: 5 days
: EXCESS.THA
: Repair
: Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	532Z
Vehicle No.:	SKL1173J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Feb 2023
Vehicle Make:	AUDI
Vehicle Model:	A6 DESIGN 2.0 TFSI (140 KW)
Primary Colour:	Grey
Manufacturing Year:	2021
Engine No.:	DKY016361
Chassis No.:	WAUZZZF20NN006334
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$42,010.00
Original Registration Date:	16 Nov 2022
First Registration Date:	16 Nov 2022
Transfer Count:	0
Actual ARF Paid:	\$50,814.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2032
PARF Rebate Amount:	\$38,110.00
COE Expiry Date:	15 Nov 2032
COE Category:	B - Car-Details at OneMotoring
COE Period (Years):	10
QP Paid:	\$115,388.00
COE Rebate Amount:	\$112,759.00
Total Rebate Amount:	\$150,869.00

The Information contained herein is correct as at 07 Feb 2023

OK

Audi A6 Mild Hybrid 2.0A TFSI S-tronic Design

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$238,000****Depreciation** ⓘ

\$22,670 /yr

[View models with similar depre](#)**Reg Date**

24-Jun-2022

(9yrs 4mths 16days COE left)

Mileage

10,000 km

Manufactured ⓘ

2021

Road Tax ⓘ

\$1,194 /yr

Transmission

Auto

Dereg Value ⓘ

\$137,408 as of today (change)

Fuel Type

Petrol-Electric

COE ⓘ

\$106,001

OMV ⓘ

\$41,876

Engine Cap

1,984 cc

ARF ⓘ

\$50,627

Curb Weight ⓘ

1,680 kg

Power

140.0 kW (187 bhp)

Type of Vehicle

Luxury Sedan

No. of Owners ⓘ

1