ASS. REC. BY: Kenneth

REF: CTZ/2300141/KV

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of Woodlands

Insured: _____

Policy No. _____

Claims No. _____

um Insured: _____ Excess: 500

(Client's Record)

ko of Veh: _____

licy Condition)

rk: The veh had commenced its repair at the time of inspection.

N/S	O/S

Market Value: 831k

ccident Rport: _____ Consistent? : Yes or No

R Seen: _____ Consistent? : Yes or No

irs: 04 days Res.: Yes or No

20 % 3 Val.: Yes or No

V / REP. / 24 HRS

Vehicle: IN / OUT

_____ Person Contacted: _____

Veh No: GBE 1520J Yr Regn: 09 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: NIS Cabstar c.c 2953

Colour Gold A/C: Insured / Std / NI / NA

Sp.Reading 234856 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISC2F247 0857565

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: Toyo 195R15X8

R: Yoko 165R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	4 mm	R/Bal.	7 mm
L/Bal.	4 mm	L/Bal.	7 mm
D.O.A.	1/2/23	D.O.I.	9/2/2023

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Action / Instruction

Rear Lt tyre puncture by sharp object causing it to punctured

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Survey Fee: _____

Transportation: $ + RS. SI

Fees

Others

TOTAL