E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722
Tel: 64560226 Fax: 64584500
GST Reg. No: 201016308K

Not Authorised
L/Lamp & ~~3150~~ 3250

ESTIMATE

Resurvey After Paint
5days

Date : 13th February 2023

M/s **G H Ong Engineering Pte Ltd**
31 Bukit Batok Crescent, #01-50
Singapore 658070

Veh No : **GBG 5942M**
Make/Model : **Nissan NV200**
Chassis No : VSKYBAM20Z0146885
Date of Acc : 13.02.23
TP Veh No : SLP 1867H

S/No	Qty	Description	Unit Price	Amount
		Materials (Nett)		
1	1 pc	Rear Tailgate RH 1102		$ 1,243.30
2	1 pc	Rear Tailgate Mechanism Lock, Lower RH		$ 124.80
3	1 pc	Rear Tailgate Hinge, Lower RH		$ 115.90
4	1 pc	Rear Tailgate Center Checker RH		$ 87.80
5	1 pc	Rear Tailgate Inner Board RH		$ 145.50
6	1 pc	Rear Bumper	Buffed	$ 524.80
7	2 pcs	Rear Bumper Bracket L/R	40.2	$ 80.40
8	1 pc	Rear Bumper Inner Sponge	CBA	$ 112.80
9	1 pc	Rear Bumper Tow Cover		$ 34.10
10	1 pc	Rear Bumper Reflector RH		$ 66.90
11	1 pc	Rear Lamp RH 340.80		$ CBA 340.80
12	1 pc	Rear Body Panel RH		$ 1,767.00
13	1 pc	Rear End Panel, ~~Inner~~ inner		$ 752.60
14	1 pc	Rear End Panel Top Garnish		$ ~~[illegible]~~ 94.30 ~~X~~ dd
15	1 pc	Rear Boot Weatherstrip	Dis Mat	$ 95.40 50%
				$ 5,586.40
			Less 10%	$ 558.64
			Parts Total :	$ 5,027.76
		Special Nett		
1	1 pc	End Panel, Outer		$ 198.00
2	1 set	Reverse Sensor		$ 280.00 200%
3	1 set	Rear Bumper Clips	New	$ 45.00
4	1 set	End Panel Top Garnish Clips		$ 35.00 nec
5	1 set	Rear Tailgate Inner Board Clips		$ 35.00
6	1 pc	Windscreen Sealant		$ 50.00 40%
7	1 set	RH Body Co's Sticker		$ 400.00
			Special Nett :	$ 845.00
		Labour		
1		To remove & rearrange electrical wirings, check lightings		$ 80.00 20%
2		To remove & replace upholstry, floor board & trim garnishes. (to facilitate repairs)		$ 100.00 60%
3		To remove, reinstal rear tailgate glass RH .		$ 100.00 60%
4		To remove, transfer tailgate components.		$ 100.00 60%
5		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.		$ 1,000.00 600%
6		Putty and respray painting on affected portions.		$ 1,000.00 600%
7		To remove & renew reverse sensor		$ 150.00 50%
8		Rust proofing on affected portions.		$ 80.00 30%
			Labour Total :	$ 2,610.00
			Total Parts & Labour :	**$ 8,482.76**

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

for E M Solution Pte Ltd

Note: *Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.*