COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO	SHC2379J	DATE:	13.12.22
MAKE	HYUNDAI	MVA	JUMANI
MODEL	I40	DOA:	10.12.22

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER ASSY Dent			$553.00	
1	REAR BUMPER UNDER COVER ? X			$228.00	
1	REAR BUMPER BEAM ? X			$428.40	
10	REAR BUMPER CLIPS nil			$22.00	
1	REAR BUMPER SPONGE ? X			$119.50	
1	REAR BUMPER MOULDING Scr			$85.00	
1	BOOTLID Scr / Dent			$2,609.80	
1	BOOTLID LOWER GARNISH nil			$227.90	
1	BOOTLID EMBLEM - I40 nil			$67.90	
1	BOOTLID EMBLEM - CRDI nil			$52.40	
1	BOOTLID EMBLEM - H nil			$63.10	
	SUB TOTAL			$4,457.00	3681.10
	LESS 20%			$891.40	736.22
	DISCOUNTED TOTAL			$3,565.60	2944.88
	BOOTLID APPS LOGO nil			$40.00	NET
	REVERSE SENSOR ? X			$135.70	NET
	BOOTLID COMFORT LOGO nil			$30.00	NET
	BOOTLID COMFORT TEL.NO LOGO nil			$30.00	NET
	SUB-TOTAL			$235.70	
	LESS 10%			$23.77	
				$213.93	
	Labour Charge				
	PANEL BEATING			$600.00	560
	SPRAY PAINT			$600.00	500
	REMOVE / REFIX REVERSE SENSOR			X? $50.00	$
	TOTAL LABOUR			$1,250.00	
	ESTIMATE TOTAL			$5,029.53	4104.88
				20% =	820.97
				=	3283.90
				T ≈	3300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4 days L/S 1 rdm

13/2/23 5PM

Powered by CamScanner