**COMFORT TRANSPORTATION PTE LTD**

**REPAIR ESTIMATE**

**Vehicle No.** : SHC2526B
**Make** : HYUNDAI
**Model** : I-40

Date: 15/02/2023
Insurance: INCOME
MVA: MS. LOKE YY

| Qty | Parts Description / Labour | Type | Unit Price | Amount | |
|---|---|---|---|---|---|
| 1 | REAR BUMPER COVER Cut ✓ | | | $ 553.00 | |
| 1 | REAR BUMPER CLIPS X NN | | | $ 22.00 | |
| 1 | REAR BUMPER REINFORCEMENT ? X NN | | | $ 428.40 | |
| 1 | RR BUMPER REFLECTOR LH Scr ✓ | | | $ 32.00 | |
| 1 | REAR BUMPER UNDER COVER ? Scr ✓ | | | $ 228.00 | |
| | **SUB TOTAL** | | | $ 1,263.40 | 813 |
| | **LESS 20%** | | | $ 252.68 | 162.60 |
| | **DISCOUNTED TOTAL** | | | **$ 1,010.72** | 650.40 |
| | REAR BUMPER RUBBER MAT New | | | $ 50.00 | Nett |
| | | | | **$ 50.00** | Nett |
| | **Labour Charge** | | | | |
| | PANEL BEATING | | | $ 300.00 | 280 |
| | SPRAY PAINTING CHARGE | | | $ 300.00 | 250 |
| | REMOVE/REFIX REVERSE SENSOR | | | $ 60.00 | 30 |
| | **TOTAL LABOUR** | | | **$ 660.00** | |
| | **ESTIMATE TOTAL** | | | **$ 1,720.72** | 1260.40 |
| | | | | 20% | = 252.08 |
| | | | | | 1008.32 |
| | | | | | ≈ 1000 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

3 days L/S
15/2/23
Infm 4.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Powered by CamScanner