LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD

10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983

ATTN: OH VALE

Ref: CS3/HSB23002075/Wwp3e2

Date: 07/03/2023

Code: HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	SHC 1862L	**Veh. Inspected**	FBS 2294G
	Policy No.	VFX/P2419138	**Coverage ($)**	0.00
	Claim No.	S3M04JP5	**Excess ($)**	0.00
	Assign From	OH VALE	**Assign Date**	24/02/2023

2. Vehicle Particulars & Condition

	Make & Model	HONDA CB400A	**c.c**	399
	Engine No.	HIDDEN	**Year of Reg.**	2021
	Chassis No.	JH2NC4295KK500234	**Colour**	RED
	Odometer	34551 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	120/60 R17	BRIDGESTONE	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.



5. General Information

	Accident Date	17/02/2023	**Inspect Date / Time**	27/02/2023 (02:30 PM)
	Survey held at	FUNMASTERS PROMOTION BLK 176, SIN MING DRIVE #03-21 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,500-$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

Report Ref No. CS3/HSB23002075/Wwp3e2

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.