LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To [illegible]
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

WBA 6V120405N 31 510.

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883
Autobay @ Kaki Bukit
Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP Liberty.
Xin Yu.

ESTIMATE

Vehicle No : SMM523K | **Make/Model : BMW 216I**
Chassis No: WBA6V120405N31510 | **Accident date : 03.12.2022**

No	DESCRIPTION	Qty		Amount (S$)	
	List Items				
1	Rear windscreen rubber New	1	$	175	✓
2	Rear tailgate Dented	1	$	1615	✓
3	Rear tailgate hinge @ $ 85 New	2	$	170.	X
4	Rear tailgate shock absorber @ $ 355 New	2	$	710.	X.
5	Rear tailgate upper lock Bent	1	$	234.	✓
6	Rear tailgate catch New	1	$	58	+
7	Rear tailgate weather strip New	1	$	272	X.
8	Rear tailgate inner board New	1	$	659.	+
9	Rear tailgate reflector @ $ 385 New	2	$	770.	+
10	Rear tailgate BMW logo New	1	$	75	✓
11	Rear tailgate "216i" emblem	1	$	78	✓
12	Rear lamp @ $ 540 New	2	$	1080.	+.
13	Rear end panel Rust	1	$	825.	+.
14	Rear end panel top garnish New	1	$	221.	+
15	Rear bumper Deformed.	1	$	1050	✓
16	Rear bumper side holder @ $ 110 (RH cracked	2	$	~~220.~~	110.
17	Rear bumper reflector @ $ 115 New	2	$	230	+
18	Rear bumper lower protector (Black) New	1	$	85	✓
19	Rear bumper reinforcement. Bent		$	655.	✓
		Less 5% Disc	$		
	4077	Total	$		
	3669.30				

	Special Nett Items				
1	Rear bumper reverse sensor @ $ 280 2 pieces damaged	4	$	~~1120~~	560.
		Total 560	$		

	Labour Cost				
1	To supply rear windscreen sealant New		$	50.00	✓
2	To supply rear end panel inner sealant New		$	200.00	X
3	Remove & reinstall rear windscreen		$	~~150.00~~	120.
4	Remove & reinstall reverse sensor		$	~~150.00~~	50.
5	Remove & reinstall bootlid inner garnish		$	~~150.00~~	60.
6	Remove & reinstall camera	1470	$	~~100.00~~	50
7	Remove ,replace & repair consistent to the accident		$	~~1,500.00~~	500
8	Respray painting		$	~~1,200.00~~	600
9	Tuff kote		$	~~100.00~~	40.
		Total	$	3,600.00	
		Grand Total	$		

Total: 5699.30
A/S: 4.5K
04 Days

4.5K