ASS. REC. BY: Marcus | REF: CS/FC1230028/Alwyn

ASSIGNMENT

From: | Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBD784B

at Workshop m/s Sam yick lian

of

Insured: Y/P 78304

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $14k. 0

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS C60fW Vehicle: IN / OUT

Date: Person Contacted: 21A6916

Veh No: GBD784B Yr Regn: 13/06/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or GA

Make: Nissan NV200 c.c 1597

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 223930 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VM20054961

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hebilead

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	22/02/23	D.O.I.	28/2/23

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Dep 17k.
6/3/23	reverse sensor never quote L/S & S/700 inhand AWSNG @ 6 days (Red $4,731.48/45%)

Date/Time, File Pass to?
1) 16/03/2023 Typist

Date/Time, File Return to?
2)

☐ : Preli. Report
☑ : Final Report

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Report Format : TP

Lump Sum / I.B.I: ($ L/S $5700)

Survey Fee:	170
Transportation:	50
__S + RS, __SI	50+50
Photos	113
Others	
TOTAL 20/3/23	433