# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD	Ref: CS3/ASM22003363/Uvy3e2
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811	Date: 23/05/2022
ATTN: KHONG LYNN	Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 8253J	Veh. Inspected	SMR 2688D
Policy No.	VFX/P2419140	Coverage ($)	0.00
Claim No.	S2M03Y9U	Excess ($)	0.00
Assign From	KHONG LYNN	Assign Date	12/04/2022

2. Vehicle Particulars & Condition

Make & Model	VOLVO V40 (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	YV1MV28H0G2296267	Colour	GREY
Odometer	104195 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	MICHELIN	6 mm
L/H Front Tyre	225/40 R18	MICHELIN	6 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

5. General Information

Accident Date	08/04/2022	Inspect Date / Time	18/04/2022 (11:30 AM)
Survey held at	1 Kaki Bukit Avenue 6 #01-87/85 Autobay S417883		
Repairer	Z-ONE AUTOMOTIVE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $6,000-$7,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**

Report Ref No. CS3/ASM22003363/Uvy3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser